

PAPERS ON ENGINEERING SUBJECTS.

No. 8. November 1927.

CONTENTS.

	PAGE
1. Furnace Brickwork - - - - -	3
2. Trailing of Turbines - - - - -	11
3. Development and Design of Condensers and Condensing Plant -	19
4. Static Balancing of Rotors - - - - -	28
5. Economy of Turbines under Cruising Conditions - - - - -	32
6. Fire Extinguishers - - - - -	43
7. Priming in Boilers - - - - -	49
8. Defects :—	
(I) Damage and Repair of an Impulse Turbine - - - - -	57
(II) Unusual Defect in a Heavy Oil Engine - - - - -	63
9. Notes :—	
(a) Oil in Boiler Feed Water - - - - -	64
(b) Effect of Tool Marks and Scratches on the Strength of Materials - - - - -	67
(c) Purity of Feed Water - - - - -	69
(d) Output of Oil Fuel Sprayers - - - - -	72
(e) Creep of Materials at High Temperatures - - - - -	74

The articles indexed under the heading of "Notes" have been compiled in response to specific requests from Engineer Officers.

It is desired that Officers will forward suggestions or inquiries regarding matters of general engineering interest, with a view to initiating future articles in these Papers. Communications of this nature should be addressed to :—
Editor of Engineering Notes, Engineer-in-Chief's Department,
Admiralty.