

INDEX

Engineering Abstracts

	Issue	Page		Issue	Page
Absorption of Gases by Welds	June	83	Aluminium-bronze Electrodes. Overlaying with	March	40
Achievements of Marine Engineering. Aims and	May	61	Aluminium Coated Steel	December	168
Accelerated Cavitation Research	September	128	Aluminium Coatings on Steel Sheet. Hot-dipped	December	160
Additive Type Lubricants. Storage	March	36	Aluminium Dipping Process	March	42
Admiralty Laboratory. Gas Turbine at	July	97	Aluminium. Percussion Welding—	March	33
<i>Aestus</i> . Survey Tender	March	30	Aluminium Sheets. Bend Test for	July	96
<i>Africana II</i> . Fisheries Research Vessel	May	67	Aluminium to Cast Iron. Bonding	March	33
Aims and Achievements of Marine Engineering... ..	May	61	Aluminium. Treatment of Burns Due to Steam, by	June	74
Air Bubbles in Liquids. Speed of Rise of	July	99	Aluminium Tripod Masts. Welded	July	91
Air Charging Cylinder. Ricardo Engine with Air Conditioning Machinery in H.M. Ships. Refrigeration and	January	10	Amazon. Plastic Coated Tug for the	February	28
Air Cooling of Diesel Engine Cylinders	February	24	American-built Ferries for Brazil	November	142
Air Distributor for Oil Burner. New	December	162	American Diesel Engines. Large	August	108
Air Heater. Fire in	July	88	American Gas Turbine Practice	September	116
Air Injector. Design and Performance of	March	38	American Liner. Electrical Installation in	April	53
Air Intake for Free-Piston Gasifiers. Pulsating	August	102	American Motor Ships. Boiler Oil in	August	108
Air Supply. Gas Turbine Combustion Chamber	October	131	American President Liners. Electrical Power Plant of New	August	110
Aircomatic Welding Process	September	128	American Ship Structure Committee	May	67
Alarm Device for Oily Water Separators... ..	April	45	American Supertanker	January	12
Alarm. Feedwater Contamination	October	136	American Turbines in Dutch Vessels	November	146
Alloy Bearings in Diesel Engines. Aluminium	November	150	Anchors. Improvements in Mooring	May	67
Alloy Cast Iron. Progress in High Duty and Alloy Pistons of Spanish Manufacture. Light Alloy Steel Containing Boron. Strength of Low Carbon, Low	March	37	Anchors. Investigations on Model	May	68
Alloys and Their Application to Shipbuilding. Aluminium	September	121	<i>Andanes</i> . Steam Trawler	June	80
Alloys. Corrosion Behaviour of Aluminium	February	20	Anticipated Distortion by Welding	December	158
Alloys. Creep and Fatigue of Copper-base... ..	September	127	Anti-corrosive Compositions in Sea Water. Performance of	September	117
Alloys. Hot Hardness of Hard-facing	July	96	Anti-corrosive Compositions. Tests for Underwater	February	24
Alloys. Joining of Aluminium	May	70	Anti-fouling Paints	June	74
Alloys. Metal Spraying of High-temperature Metals and	September	127	Apparatus for Studying Loop Scavenging. Test	February	24
Alloys. Shielded Stud Welding of Aluminium	April	54	Application of Aluminium Alloys to Shipbuilding	March	39
Alloys. Thermal Shock Test of High Temperature	December	168	Application of Diesel Features to Steam Engines	September	118
Alloys to Other Metals. Welding High-nickel	April	54	Application of Gas Turbine Technique to Steam Power	April	50
Alloys to Shipbuilding. Application of Aluminium	March	39	Application of Inlet Grilles to Ventilating Systems	November	143
Aluminium Alloy Bearings in Diesel Engines Aluminium Alloys and Their Application to Shipbuilding	November	150	Application of Photo-elastic Methods to Ship Design Problems	January	9
Aluminium Alloys. Corrosion Behaviour of Aluminium Alloys. Joining of	December	158	Arctic Patrol Vessel. New	February	28
Aluminium Alloys. Shielded Stud Welding of	June	84	Arc Underwater Welding	March	38
Aluminium Alloys to Shipbuilding. Application of	May	70	Arc Welding. Control of Distortion in	July	93
	March	39	Arc Welding in Spanish Naval Shipyards	May	70
			Arc Welding of Butt Welds	October	129
			Arc Welding Process. New Hidden	November	156
			Arc Welds in Mild Steel. Ductility of	December	159
			Argentine. Italian Motorship for the	December	166
			Argentine Motorship. Fast	May	65

	Issue	Page		Issue	Page
Arrangement of Corrugated Bulkheads ...	September	113	Box Girder. Locked-in Stresses in Welded	November	156
Ash. Corrosion of Heat Resisting Steels by Vanadium Containing Oil ...	September	117	Brazil. American-built Ferries for ...	November	142
<i>Atlantic Engineer</i> . New Tanker ...	December	165	Brazing ...	May	71
Atlas Diesel Engine Governor ...	May	63	Brazing and Welding Coated Materials ...	September	128
Atomic Energy. Mechanical Engineering in Atomic Power and Ship Propulsion ...	July	92	<i>Breconshire</i> Raised Off Malta ...	November	147
Atomisers. Rotating Cup Type ...	April	50	British Built Liner for French Service ...	November	141
Atomizing Burners. Steam ...	January	8	British Built Swedish Steam Tanker ...	July	89
Austenitic and Ferritic Steam Piping. Thermal Shock Tests of ...	March	37	British Shipbuilding Research Association. First Six Years of ...	September	124
Australia. Shipbuilding in ...	July	99	Buckles on Strength in Welded Ships. Effect of ...	April	49
Australia's Towing Tanks ...	September	125	Buckling of Compressed Steel Member ...	May	71
Automatic De-gasser for Steam Sampling ...	July	89	Buckling of Eccentrically Loaded Columns...	April	54
Automatic Steering Control ...	April	54	Bulk Carrier. Single-cylinder Turbine for Great Lakes ...	November	146
Auxiliary Diesel Engines for Increasing Gas Turbine Compressor Output ...	November	147	Bulkheads. Arrangement of Corrugated ...	September	113
Auxiliary Turbo-generators ...	July	97	Buoyancy Characteristics ...	May	72
	February	23	Buoy Tender. New Canadian Lighthouse and ...	July	91
Balanced-pressure Engine Indicator ...	July	85	Burner. Marine Oil ...	September	122
Ball and Roller Bearings. Lubrication of ...	July	91	Burners. Steam Atomizing ...	March	37
Ballasted Cargo Vessels. Shifting Boards for <i>Balmoral</i> . Twin-screw Passenger Vessel ...	May	66	Burns Due to Steam, by Aluminium. Treatment of ...	June	74
<i>Baltrover</i> . Refrigerated Cargo Vessel ...	February	28	Butt Welds. Arc Welding of ...	October	129
Band-sawing of Stainless Steel. Friction ...	December	164			
Barges. Optimum Screw Propulsion for Self-propelled ...	February	22	Cable Ship <i>Edward Wilshaw</i>	January	8
	July	99	Cable Ship. New French ...	September	128
Barges. Structural Strength of River ...	September	125	Calculated v. Measured Wave Making of Hull Forms ...	December	167
Barges. Voith Schneider Pusher Unit for Dumb ...	August	111	Canadian-built Coasters for Venezuela ...	June	79
Bearings. Effect of Macro-roughness on Performance of Parallel Thrust... ..	June	82	Canadian-built Motor Vessels ...	February	18
Bearings in Diesel Engines. Aluminium Alloy	November	150	Canadian Lighthouse and Buoy Tender. New ...	July	91
Bearings. Lubrication of Ball and Roller ...	July	91	Cantilever-bending Method. Creep Testing by a ...	October	130
Bearings. New Reliner for Diesel ...	April	53	Carbon Dioxide. Corrosive Effect of ...	November	146
Bearings. Oil Holes in Journal ...	November	155	Carbon, Low Alloy Steel Containing Boron. Strength of Low... ..	February	20
Bend Test for Aluminium Sheets ...	July	96	Carbon Piston Rings ...	November	154
Bending and Torsion of I Beam. Combined	April	55	Cargo Boats. Multi-engine Propelled French	May	65
Bethlehem Supertankers ...	August	110	Cargo Booms. Testing ...	February	28
Bibliography on Sprays ...	February	24	Cargo Distribution in Tank Vessels ...	March	31
Bilge Pump ...	May	61	Cargo Liner <i>Helenuis</i> . Passenger and ...	March	30
Blades. Production of Gas Turbine ...	September	115	Cargo Liner. New Cunard ...	November	152
Blading. Vibration of Marine Turbine ...	May	57	Cargo Liner <i>Ulysses</i> . Geared Turbine ...	January	7
Blower Uses Refractories. Flue Dust ...	April	55	Cargo Liners—Development and Maintenance. Diesel Engine Propulsion of ...	April	50
Boiler and Steam Superheater. Water Tube	May	66	Cargo Oil Stripping Pumps ...	April	52
Boiler. Composite Waste-heat and Oil-fired	January	5	Cargo Protection ...	November	141
Boiler Drums. Experimental Data on ...	September	124	Cargo. Significant Factors in Economic Handling of ...	December	163
Boiler Drums. Fusion-welded ...	June	77	Cargo Vessel <i>Baltrover</i> . Refrigerated ...	December	164
Boiler Drums. Hydraulic Fatigue Testing of	September	123	Cargo Vessel. Fast ...	March	30
Boiler Feed Pumps for Marine Service ...	March	35	Cargo Vessel. New ...	January	8
Boiler Fuels for Marine Diesel Engines ...	July	88	Cargo Vessels. Further Tests with Models of Fast ...	April	55
Boiler of the Double-flow Type. Watertube	January	15	Cargo Vessels. New German ...	February	17
Boiler Oil in American Motor Ships ...	August	108	Cargo Vessels. Shifting Boards for Ballasted	May	66
Boiler Plant. Economizer for Trawler ...	October	136	Cargo Vessels. Systematic Tests with Models of ...	December	166
Boiler Surface. Fly-ash Erosion of ...	January	16	Carrier. Single-cylinder Turbine for Great Lakes Bulk ...	November	146
Boiler Tubes. Pressure Welding of ...	February	20	Carriers. New Ore ...	September	124
Boilers. Cooling Effect of Tube Holes in Thick Shells of Marine ...	December	163	Castings. Lost Wax Process of Precision ...	March	39
Boilers for Large Great Lakes Ore Carrier ...	January	6	Castings. Repair of ...	March	32
Boilers. Dry and Wet Storage of ...	May	58	Cast Iron. Fatigue Tests on ...	July	94
Boilers. Localized Formation of Magnetic Iron Oxide in ...	September	123	Cast Iron. Stress Relief by Heat Treatment of ...	November	143
Boilers. Oil-fired Marine ...	August	109	Cast Iron. Bonding Aluminium to ...	March	33
Boilers. Testing of ...	May	66	Cast Iron. Progress in High Duty and Alloy	March	37
Boilers. Welding in ...	October	129	Catalytic Combustion... ..	August	104
Boilers. Yarrow Three-drum Water-tube ...	September	122	Cathodic Protection of Marine Tractor ...	March	40
Bolt Stresses. Initial ...	December	165			
Bonding Aluminium to Cast Iron ...	March	33			
Booms. Testing Cargo ...	February	28			
Booster Propulsion Plant. Gas Turbine ...	July	96			
Boron. Strength of Low Carbon, Low Alloy Steel containing ...	February	20			

	Issue	Page		Issue	Page
Cathodic Protection of Ship in Sea Water	October	132	Compressibility Effect in Hydraulic Servo-		
Cavitation Erosion. Testing Resistance to ...	May	69	mechanisms	December	168
Cavitation on Screw Propellers	November	146	Compression Pressure Indicator. Combustion and	July	92
Cavitation Problems	October	132	Compressor Performance. Effect of Internal Cooling Upon Centrifugal	June	82
Cavitation Research. Accelerated	September	128	Compressors. Internal Liquid Cooling of Centrifugal	November	141
Cavitation Tank. Swedish	October	137	Compressors. Theory of Valves for	December	168
Cavitation Tests. Effect of Gas Content of Sea Water upon	September	119	Condenser. Cleaning the Steam Side of a	May	58
Cementiferous Paints	June	74	Considerations in Provision and Operation of Overseas Mail Service	March	37
Centrifugal Compressor Performance. Effect of Internal Cooling Upon	June	82	Contamination Alarm. Feedwater	October	136
Centrifugal Compressors. Internal Liquid Cooling of	November	141	Content of Diesel Fuels. Sulphur	October	136
Centrifugal Pump. Flow Conditions in	December	165	Continuous Viscosity Controller	November	154
Ceramics in Gas Turbines. Outlook for	April	56	Control of Distortion in Arc Welding	July	93
Chain Drives. Roller	March	41	Controllable Pitch Propeller in Collier	August	107
Chain Locker Dry. To Keep	October	133	Controllable Propeller System and Reduction Gear Unit... ..	January	2
Channel for Ship-model Tests. Circulating Water	February	18	Controller. Continuous Viscosity	November	154
Channel Grid-stiffener System	February	23	Cooling Effect of Tube Holes in Thick Shells of Marine Boilers	December	163
Channel Motor Train Ferry. First English	November	151	Cooling of Centrifugal Compressors. Internal Liquid	November	141
Chromium Diffusion. Steel Protection by	October	131	Cooling of Diesel Engine Cylinders. Air	February	24
Chromium-plated Piston Rings	March	40	Cooling Rates in Arc Welds	March	32
Chusan. Stabilizing Gear in the	September	114	Cooling Systems. Corrosion Problems in Sea-water	October	132
Circular Cylinder Stresses	May	69	Cooling Upon Centrifugal Compressor Performance. Effect of Internal	June	82
Circulating Water Channel for Ship-model Tests	February	18	Copper-base Alloys. Creep and Fatigue of Copper Circulating Piping. Corrosion of	July	96
Clad Metal for Heat Resisting Applications	July	95	Corrosion Behaviour of Aluminium Alloys	June	84
Clan Shaw. Turbine Steamship	June	75	Corrosion Behaviour of Different Sea-waters. Relative	June	73
Clark-Sulzer Engine. First	March	29	Corrosion Fatigue	September	117
Cleaning Steam Turbines	January	3	Corrosion. Fretting	April	54
Cleaning the Steam Side of a Condenser	May	58	Corrosion. Influence of Stress upon	November	145
Closed-cycle Gas Turbine. Experimental	May	59	Corrosion of Copper Circulating Piping	July	99
CO ₂ Recorders. Comparative Tests on	October	136	Corrosion of Iron and Steel in Sea Water	December	160
Coal. Residual Oil and Pulverised	May	58	Corrosion. Jet-impingement Apparatus for Assessing	October	132
Coastal Passenger Ships with Variable Pitch Propeller	February	18	Corrosion of Heat Resisting Steels by Vanadium Containing Oil Ash	September	117
Coasters for Venezuela. Canadian-built	June	79	Corrosion of Iron Due to Temperature Differences. Galvanic	September	116
Coastwise Passenger Service. New	August	111	Corrosion of Metals by Insecticidal Solution	September	116
Coated Materials. Brazing and Welding	September	128	Corrosion of Propeller Shafts	August	104
Coated Steel. Aluminium	December	168	Corrosion of Steel in Estuarine Tropical Waters	September	117
Coating for Metal. Resin	March	42	Corrosion Problems in Sea-water Cooling Systems	October	132
Coating System Sought. Weather Deck	September	127	Corrosion Test. New	December	161
Coatings in Sea Water. Electro-chemical Study of Paint	April	55	Corrosion Testing Station. Work at	January	11
Coatings on Steel Sheet. Hot-dipped Aluminium	December	160	Corrosion Tests. Stress	March	42
Cold Starting of High Speed Diesels	October	136	Corrosive Effect of Carbon Dioxide	November	146
Collier. Controllable Pitch Propeller in	August	107	Corrugated Bulkheads. Arrangement of	September	113
Columns. Buckling of Eccentrically Loaded	April	54	Coupling. Powder	June	81
Combating Piston Ring Wear	January	15	Crankcase Lubricating Oils. Performance of Crankcase Oil Tester. Photo-electric	March	39
Combined Bending and Torsion of I Beam	April	55	Crankcase Safety Precautions. Diesel Engine	November	154
Combined Gas and Steam Turbine	November	145	Creep and Fatigue of Copper-base Alloys	July	96
Combustion and Compression Pressure Indicator	July	92	Creep Testing by a Cantilever-bending Method	October	130
Combustion. Catalytic	August	104	Cross-Channel Motorship. Danish... ..	August	112
Combustion Chamber Air Supply. Gas Turbine	October	131	Cross-Channel Ship. Single-casing Turbines for	October	139
Combustion Chambers for Marine Gas Turbines	February	22	Crossley-engined Ship. Largest	October	135
Combustion in Diesel Engine Fuel	November	150	Cunard Cargo Liner. New	November	152
Combustion in Vitiated Atmospheres	May	72	Cup Type Atomizers. Rotating	January	8
Combustion of Gas Oil	November	143	Cutter Dredger for France. Dutch Suction	August	111
Comparative Efficiencies of Internal Combustion Engines	September	120	Cycloidal Propulsion	January	1
Comparative Tests on CO ₂ Recorders	October	136			
Composite Ships. Thermal Expansion Effects in	May	68			
Composite Waste-heat and Oil-fired Boiler... ..	January	5			
Composition of Diesel Exhaust Gases	October	135			
Compound Internal Combustion Engines	January	14			
Compressed Steel Member. Buckling of	May	71			

	Issue	Page		Issue	Page
Cylinder Liner Wear. Theory of ...	February	25	Diesel Engine. Seven-cylinder Opposed Piston ...	July	88
Cylinder Liners. Water Side Deterioration of Diesel Engine ...	September	120	Diesel Exhaust Gases. Composition of ...	October	135
Cylinder. Ricardo Engine with Air Charging	April	45	Diesel-engined Ship. First Gray Polar ...	May	63
Cylinder Stresses. Circular ...	May	69	Diesel-engined Tanker <i>Randfjonn</i> ...	October	140
Cylinders. Air Cooling of Diesel Engine ...	February	24	Diesel Engines. Aluminium Alloy Bearings in ...	November	150
Cylinders. Metal Transfer from Piston Rings to ...	October	134	Diesel Engines. Boiler Fuels for Marine ...	July	88
Damage from Use of Heavy Oils as Engine, Boiler and Turbine Fuels ...	December	165	Diesel Engines for Increasing Gas Turbine Compressor Output. Auxiliary ...	July	97
Danish Cross-Channel Motorship ...	August	112	Diesel Engines, Large American ...	August	108
Danish Marine Gas Turbine...	January	3	Diesel Engines. Tracing Defects in ...	January	12
De-aerator. Investigation of Direct-contact Type ...	February	26	Diesel Exhaust Pyrometer ...	January	5
Deck Coating System Sought. Weather ...	September	127	Diesel Features to Steam Engines. Application of ...	September	118
Deck Machinery. Hydrodynamic Transmission for Marine ...	January	11	Diesel for Norwegian Vessel. German ...	August	107
Decks of Ships. Strength of ...	June	80	Diesel Fuel Testing ...	November	154
Decks. Rolling Wing ...	December	164	Diesel Machinery. Development of High-powered ...	May	59
Defects in Diesel Engines. Tracing ...	January	12	Diesel-oil Fuel Tank. Explosion of Empty	December	159
Deflection of Ships' Hulls. Rivet Slip, Stress Distribution, and the ...	February	19	Diesel Propelling Machinery. Geared ...	October	134
De-gasser for Steam Sampling. Automatic	April	54	Diesel Ship. Small Geared ...	March	42
Dehumidification. Practical Ship ...	January	9	Diesels. Cold Starting of High Speed ...	October	136
Dependence of Wake on Shape of Rudder, Trim and Stern Wave ...	April	56	Diffusion. Steel Protection by Chromium...	October	131
Derricks. Tests on Stayed Masts with Heavy	June	80	Direct-contact Type De-aerator. Investigation of ...	February	26
Descaling of Tanks. Electrolytic ...	July	95	Disk. Properties of Gas Turbine Rotor ...	February	22
Design and Performance of Air Injector ...	March	38	Distortion by Welding. Anticipated ...	December	158
Design and Performance of Internal-combustion Engines. Effect of Size on ...	October	134	Distortion in Arc Welding. Control of ...	July	93
Design for Laminar Flow. Hull ...	August	112	Distortion in Welding. Shrinkage ...	October	129
Design for Tanker. Rudder of Novel ...	September	113	Distributor for Oil Burner. New Air ...	December	162
Design. New Rudder ...	April	46	Doors. Round... ..	November	150
Design of a Class of 28,000-ton Tankers ...	March	30	Double-acting Two-stroke Engine Installation ...	March	42
Design of Hotel Services for Passenger Ships	February	28	Double-acting Two-stroke Engines of Passenger Liner <i>Oslofjord</i> ...	February	25
Design of Modern Tanker with Special Reference to Machinery ...	March	31	Double-flow Type. Watertube Boiler of the Doxford Engine during Last Decade. Development of ...	January	15
Design of Propellers ...	August	104	Doxford Engine for Smaller Vessels... ..	April	47
Design of Seakindly Ships ...	April	53	Doxford Engine Trials on Heavy Fuel ...	January	13
Design Problems. Application of Photoelastic Methods to Ship ...	September	114	Doxford Engine Using Heavy Fuel. Tests of Standard ...	June	76
Design. Tug ...	January	9	Dredge <i>Essayons</i> . Seagoing Hopper ...	February	24
Detector. Portable Leak ...	December	164	Dredger for France. Dutch Suction Cutter	February	22
Detector. Refrigerant Leak ...	August	111	Dredger. New Suction ...	August	111
Detector. Ultrasonic Flaw ...	December	33	Dredger. New Suction ...	December	159
Deterioration of Diesel Engine Cylinder Liners. Water Side ...	March	33	Drums. Experimental Data on Boiler	September	124
Development of Doxford Engine during Last Decade ...	December	161	Drums. Hydraulic Fatigue Testing of Boiler	September	123
Development of High-powered Diesel Machinery ...	May	59	Dry and Wet Storage of Boilers ...	May	58
Diesel Bearings. New Reliner for ...	April	47	Dry Film Lubrication ...	May	69
Diesel Driven Heat Pump Evaporator ...	April	53	Dry Lubrication Process. Impregnated ...	November	155
Diesel-electric Motorship ...	March	43	Dryness Fraction of Steam ...	April	46
Diesel Electric Propulsion of Ships ...	January	8	Ductility in Welding Ship-plate. Relative... ..	May	72
Diesel-electric Tug. New ...	March	38	Ductility of Arc Welds in Mild Steel ...	December	159
Diesel Engine Crankcase Safety Precautions	November	151	Dumb Barges. Voith Schneider Pusher Unit for ...	August	111
Diesel Engine Cylinder Liners. Water Side Deterioration of ...	April	53	Dust Blower Uses Refractories. Flue ...	April	55
Diesel Engine Cylinders. Air Cooling of ...	September	120	Dust Collectors. Reduction of Pressure Drop in Vortex ...	June	81
Diesel Engine for Tankers. Large ...	September	120	Dutch Ferries with Variable-pitch Propellers	November	148
Diesel Engine. Fuel Combustion in... ..	February	24	Dutch Suction Cutter Dredger for France...	August	111
Diesel Engine Governor. Atlas ...	June	76	Dutch Vessels. American Turbines in ...	November	146
Diesel Engine. Hexagonal Multi-Cylinder	November	150	Dynamometer. New Propeller ...	March	41
Diesel Engine. New Mirrlees ...	May	63	Eccentrically Loaded Columns. Buckling of	April	54
Diesel Engine Plant. Fiat Geared ...	October	133	Economic Handling of Cargo. Significant Factors in ...	December	163
Diesel Engine Propulsion of Cargo Liners—Development and Maintenance ...	May	57	Economizers for Trawler Boiler Plant ...	October	136
Diesel Engine Research ...	August	107	<i>Edward Wilshaw</i> . Cable Ship ...	January	8
	April	50	Effect of Buckles on Strength in Welded Ships ...	April	49
	December	162	Effect of Fatigue on Transition Temperature	May	72

	Issue	Page		Issue	Page
Effect of Gas Content of Sea Water upon Cavitation Tests	September	119	Fatigue Testing of Boiler Drums. Hydraulic Fatigue Tests on Cast Iron	September	123
Effect of Macro-roughness on Performance of Parallel Thrust Bearings	June	82	Feed Pumps for Marine Service. Boiler	July	94
Effect of Internal Cooling Upon Centrifugal Compressor Performance	June	82	Feedwater Contamination Alarm	March	35
Effect of Size on Design and Performance of Internal-combustion Engines	October	134	Ferries for Brazil. American-built	October	136
Efficiency of Planetary Gears	November	155	Ferries, Reversible Propellers for Scheldt	November	142
Elbows. Use of Turning Vanes at Sharp	November	154	Ferries with Variable-pitch Propellers. Dutch Ferritic Steam Piping. Thermal Shock Tests of Austenitic and	June	79
Electric Propulsion Regulating Device	November	148	Ferry Boats Built Upside Down	November	148
Electric Welding and Cutting Under Water in the Soviet Union	June	83	Ferryboats. New York	July	99
Electrical Distribution on Shipboard	August	105	Ferry, First English Channel Motor Train Ferry for State of Michigan. Ice-breaking... ..	September	124
Electrical Installation in American Liner	April	53	Fiat Geared Diesel Engine Plant	September	125
Electrical Measurement of Torque	January	11	Film Lubrication. Dry	November	151
Electrical Power Plant of New American President Liners	August	110	Finnish Ice-breaker. Large	September	126
Electro-chemical Study of Paint Coatings in Sea Water... ..	April	55	Fire in Air Heater	August	107
Electrode. Heating	June	83	Firefloats	May	69
Electrodes. Overlaying with Aluminium-bronze	March	40	Fires and Explosions. Ultrasonic Vibrations as Possible Sources of	November	142
Electrolytic Descaling of Tanks	July	95	First Clark-Sulzer Engine	July	88
Elongation of Pre-stressed Parts. Measuring Embrittlement of Weld Metal	July	92	First English Channel Motor Train Ferry	July	98
English Channel Motor Train Ferry. First Epicyclic Gearing	December	160	First Gray Polar Diesel-engined Ship	September	116
Epicyclic Gears. Strain Gauge Tests on	November	151	First Multiplex Engine	March	29
Erosion of Boiler Surface. Fly-ash	April	51	First Six Years of British Shipbuilding Research Association	November	151
Erosion. Testing Resistance to Cavitation	October	130	First Spanish-built Sulzer Engine	May	63
Estuarine Tropical Waters. Corrosion of Steel in	November	155	Fish Processing Plant. Fishing Vessel with Fisheries Research Vessel <i>Africana II</i>	August	109
Etching Process. New	April	51	Fishing Grounds. Freezing at the	September	124
Evaporator. Diesel Driven Heat Pump	January	16	Fishing Vessel with Fish Processing Plant	January	5
Examination of Surfaces	May	69	Five-bladed Propellers... ..	October	140
Exhaust Gases. Composition of Diesel Engines. Sulphur-containing	September	117	Flame Cutting... ..	May	67
Exhaust Gases of Internal Combustion Engines. Heated Gas-turbine Cycle	January	9	Flame Cutting Process. Oxy-kinetic	April	52
Exhaust Pipes. Research on... ..	March	43	Flame Radiation. International Research on Flame Straightening and Forming Structural Steel	October	140
Exhaust Process in Four-stroke I.C. Engines	March	42	Flashing Mixture of Water and Steam. Flow of	November	147
Exhaust Pyrometer. Diesel	April	56	Flaw Detector. Ultrasonic	May	71
Expansion Effects in Composite Ships. Thermal	October	135	Flow Conditions in Centrifugal Pump	August	101
Experimental Closed-cycle Gas Turbine	December	165	Flow Measurement. Fluid	August	103
Experimental Data on Boiler Drums	June	84	Flow of Flashing Mixture of Water and Steam	December	162
Experimental Robot Lightship	September	121	Flue Dust Blower Uses Refractories... ..	December	161
Experiments with Models of High Speed Ships	December	162	Fluid Flow Measurement	December	165
Explosion of Empty Diesel-oil Fuel Tank	January	5	Fluid Friction in Viscous Flow Across Tube Banks. Heat Transfer and	March	38
Explosion Testing of Welded Joints	May	68	Fly-ash Erosion of Boiler Surface	December	162
Explosions. Ultrasonic Vibrations as Possible Source of Fires and	May	59	Formation of Magnetic Iron Oxide in Boilers. Localized	April	55
Exposure Trials of Weatherwork Paints	September	116	Fouling Organisms. Studies on Marine	March	38
Fabrication. Surface Preparation of Mild Steel Prior to	February	23	Four-stroke I.C. Engines. Exhaust Process in	January	16
Failures of Ships. Structural	December	159	Fraction of Steam. Dryness	December	162
Fast Argentine Motorship	June	82	France. Dutch Suction Cutter Dredger for France. Gas Turbine Progress in	April	46
Fast Cargo Vessel	September	121	Freezing at the Fishing Grounds	August	111
Fast Cargo Vessels. Further Tests with Models of... ..	December	162	French Cable Ship. New	November	144
Fatigue. Corrosion	May	67	French Cargo Boats. Multi-engine Propelled French Naval Gas Turbine	January	12
Fatigue of Copper-base Alloys. Creep and Fatigue on Transition Temperature. Effect of	May	72	French Passenger Motorship <i>La Marseillaise</i> French River Tug. Large	April	52
Fatigue Strength of Joints	September	117	French Service. British Built Liner for Fretting Corrosion	September	128
Fatigue Test. Single Gear Tooth Bending	July	96	Friction and Heat Transfer in Tubes	May	65
	May	72	Friction Band-sawing of Stainless Steel	June	73
	December	160	Friction in Viscous Flow Across Tube Banks. Heat Transfer and Fluid	October	140
	May	57	Friction of Lubricating Oils. Kinetic Boundary	March	43
				November	141
				April	54
				April	55
				February	22
				March	35
				January	9

	Issue	Page		Issue	Page
Fuel Combustion in Diesel Engine	November	150	Gear in the <i>Chusan</i> . Stabilizing	September	114
Fuel Injection System. Pilot	August	108	Gear. Marine Reversing	February	23
Fuels. Sulphur Content of Diesel	October	136	Gear Tooth Bending Fatigue Test. Single	May	57
Fuel Tank. Explosion of Empty Diesel-oil	December	159	Gear-tooth Stresses at High Speed	May	69
Fuel Testing. Diesel	November	154	Gear Unit. Controllable Propeller System		
Fuels. Damage from Use of Heavy Oils as			and Reduction	January	2
Engine, Boiler and Turbine	December	165	Gears. Efficiency of Planetary	November	155
Full-scale Check on Model Tests	August	104	Gears. Modern Marine	August	103
Full-scale Trials of Schnitger Propellers ...	August	104	Gears. Nested-type Reduction	December	161
Funnel Design and Smoke Abatement	July	90	Gears. Strain Gauge Tests on Epicyclic ...	April	51
Funnel. Ship's	November	153	Geared Diesel Engine Plant. Fiat	August	107
Further Tests with Models of Fast Cargo			Geared Diesel Propelling Machinery	October	134
Vessels	April	55	Geared Diesel Ship. Small	March	42
Fusion-welded Boiler Drums	June	77	Geared Steam Engine... ..	May	64
Future Power Plant Possibilities	December	166	Geared Steam Turbines for Merchant Ship		
			Propulsion	May	62
Galvanic Corrosion of Iron Due to Tempera-			Geared Turbine Cargo Liner <i>Ulysses</i> ...	January	7
ture Differences	September	116	Gas Turbine Plant	January	10
Gamma Rays	February	20	Geared Turbine Plant. Torsional Vibra-		
Ganges. Paddle Steamer for River	July	93	tions in	July	88
Gas and Steam Turbine. Combined	November	145	Geared-turbine Ship. Lubrication Oil Failure		
Gas Content of Sea Water upon Cavitation			on	January	11
Tests. Effect of	September	119	Gearing, Epicyclic	April	51
Gas Oil. Combustion of	November	143		October	130
Gas Pressure Pulsations. Vibration of Piping				November	155
Caused by	March	42	Geometrical Variation of Ship Forms.		
Gas Streams. Temperature Measurements in			Systematic	August	104
High Velocity	April	49	German Cargo Vessels. New	February	17
Gas Turbine at Admiralty Laboratory	July	97	German Diesel for Norwegian Vessel ...	August	107
Gas Turbine Blades. Production of	September	115	Girder. Interaction between Superstructure		
Gas Turbine Booster Propulsion Plant	July	96	and Main Hull	February	18
Gas Turbine Combustion Chamber Air			Girder. Locked-in Stresses in Welded Box	November	156
Supply	October	131	Governor. Atlas Diesel Engine	May	63
Gas-turbine Cycle. Exhaust-heated	June	84	Grain Division. Mezzo-deck	December	157
Gas Turbine. Danish Marine	January	3	Gray Polar Diesel-engined Ship. First ...	May	63
Gas Turbine Design. World Progress in ...	June	73	Great Lakes Bulk Carrier. Single-cylinder		
Gas Turbine. Experimental Closed-cycle ...	May	59	Turbine for	November	146
Gas Turbine. French Naval	June	73	Great Lakes Ore Carrier. Boilers for Large	January	6
Gas-turbine Fuels. Properties of	January	8	Great Lakes Steamships. United Kingdom—	January	6
Gas Turbine Installation	May	60	Grid-stiffener System. Channel	February	23
Gas Turbine. Oerlikon Radial	November	145	Grilles to Ventilating Systems. Application		
Gas Turbine Operation at 1,500 deg. F. ...	March	35	of Inlet	November	143
Gas Turbine Plant. New	September	115	Guards. Propeller	August	105
Gas Turbine Plant. Ventilated Thermal			Gyro-propulsion	May	62
Insulation for Marine	March	43			
Gas Turbine Practice. American	September	116	"Harbormaster" Propelling Units	October	135
Gas Turbine Progress in France	November	144	Hardness of Hard-facing Alloys. Hot ...	September	127
Gas-turbine Research. Marine	August	102	Hatch Covers. Ships'	June	78
Gas Turbine Rotor Disk. Properties of ...	February	22	Heat Exchanger System for Gas Turbines ...	February	22
Gas Turbine. Ruston	March	44	Heat Pump Evaporator. Diesel Driven ...	March	43
Gas Turbine Self-Starter	May	58	Heat Resisting Applications. Clad Metal for	July	95
Gas Turbine Technique to Steam Power.			Heat Resisting Steels by Vanadium Contain-		
Application of	April	50	ing Oil Ash. Corrosion of	September	117
Gas Turbine Tests. John Brown	July	97	Heat Transfer and Fluid Friction in Viscous		
Gas Turbine Using Two Types of Machine			Flow Across Tube Banks	March	35
Gas Turbines. Combustion Chambers for			Heat Transfer in Tubes. Friction and ...	April	55
Marine	February	22	Heat Treatment of Cast Iron. Stress Relief		
Gas Turbines. Heat Exchanger System for			by	November	143
Gas Turbines. Japanese	September	115	Heated Metals. Machining of	August	103
Gas Turbines. Outlook for Ceramics in ...	April	56	Heater. Fire in Air	July	88
Gas Turbines. Reversible Transmission ...	March	34	Heating Electrode	June	83
Gases by Welds. Absorption of	June	83	Heavy Fuel. Doxford Engine Trials on ...	June	76
Gases. Composition of Diesel Exhaust ...	October	135	Heavy Fuel. Running Motor Vessels on ...	November	142
Gases. Transient Flow of	March	35	Heavy Fuel. Tests of Standard Doxford		
Gasifier and Turbine. Free Piston	January	12	Engine Using	February	24
Gasifiers. Pulsating Air Intake for Free-			Heavy Oils as Engine, Boiler and Turbine		
Piston	August	102	Fuels. Damage from Use of	December	165
Gaskets and Bolted Joints	March	32	<i>Helenuis</i> . Passenger and Cargo Liner ...	March	30
Gate Valve Motor	March	31	Hexagonal Multi-cylinder Diesel Engine ...	October	133
Gauge Tests on Epicyclic Gears. Strain ...	April	51	Hidden Arc Welding Process. New	November	156
Gauges. Resistance-type Strain	August	112	High Duty and Alloy Cast Iron. Progress		
Gear Case Moisture Control	December	161	in	March	37

	Issue	Page		Issue	Page
High Frequency Notch Bend Test	June	82	Injector Pump. Hydraulic Servo	January	4
High-nickel Alloys to Other Metals. Welding	April	54	Injection. Two-stage	August	109
High-powered Diesel Machinery. Develop-	May	59	Inlet Grilles to Ventilating Systems. Appli-	November	143
ment of	July	99	cation of	October	131
High-pressure Steam Safety Valve. Sealing	October	136	Inlets in Ventilation. Jets and	September	116
of	September	119	Insecticidal Solution. Corrosion of Metals	March	43
High Speed Diesels. Cold Starting of	May	67	by	December	161
High Speed Reciprocators	February	23	Insulation for Marine Gas Turbine Plant.	February	18
High Speed Ships. Experiments with	December	168	Ventilated Thermal	September	120
Models of... ..	September	127	Insulation. Thermal	January	14
High-speed Steam Reciprocators for Ships ...	March	43	Interaction between Superstructure and Main	October	134
High Temperature Alloys. Thermal Shock	April	49	Hull Girder	December	165
Test of	January	10	Internal Combustion Engines. Comparative	November	141
High-temperature Metals and Alloys. Metal	September	127	Efficiencies of	August	103
Spraying of	September	127	Internal Combustion Engines. Compound	February	26
High Temperature. Metals at	March	43	Internal-combustion Engines. Effect of Size	May	68
High Velocity Gas Streams. Temperature	April	49	on Design and Performance of	December	160
Measurements in	January	10	Internal Combustion Engines. Sulphur-con-	March	32
H.M. Ships. Refrigeration and Air Condi-	September	127	taining Exhaust Gases of	March	33
tioning Machinery in	November	155	Internal Liquid Cooling of Centrifugal Com-	March	32
Holds. Ventilation of Ships'	July	87	pressors	September	116
Holes in Journal Bearings. Oil	February	22	International Research on Flame Radiation	July	94
Holt Ships. 8,000 s.h.p. Propelling Machi-	April	55	Investigation of Direct-contact Type De-	September	123
nery for Two	March	34	erator	March	37
Hopper Dredge <i>Essays</i> . Seagoing	December	160	Iron and Steel in Sea Water. Corrosion of	February	25
Horse-power-hour Meter. Marine Shaft ...	September	127	Iron and Steel. Percussion Welding—	December	166
Hot Air Turbine Ship's Propulsion Plant... ..	December	160	Iron. Bonding Aluminium to Cast	September	116
Hot-dipped Aluminium Coatings on Steel	September	127	Iron Castings. Repair of	July	94
Sheet	December	160	Iron Due to Temperature Differences. Gal-	September	123
Hot Hardness of Hard-facing Alloys	September	127	vanic Corrosion of	March	37
Hot Radiography	December	160	Iron. Fatigue Tests on Cast	February	25
Hotel Services for Passenger Ships. Design	March	31	Iron Oxide in Boilers. Localized Formation	December	166
of	August	112	of Magnetic	September	118
Hull Design for Laminar Flow	September	113	Iron. Progress in High Duty and Alloy Cast	November	143
Hull Forms. Calculated v. Measured Wave	December	167	Isotopes as Engineering Tools	January	9
Making of	February	18	Italian Motorship for the Argentine	October	137
Hull Girder. Interaction between Super-	April	55	<i>Kairouan</i> . Turbo-electric Machinery of the	June	80
structure and Main	February	19	Keyways. Torsion of Shaft with	September	115
Hull Tests. Scale Effect Experiments on	December	164	Kinetic Boundary Friction of Lubricating	October	132
Twin Screw	June	79	Oils	October	131
Hulls. Rivet Slip, Stress Distribution, and	May	61	Kort Nozzles for Icebreakers... ..	July	97
the Deflection of Ships'	September	123	Japanese-built 17-knot Liner	May	70
Hulls. Vinyl Protection for Ships'	January	4	Japanese Gas Turbines	June	82
Hulls. Water-blast Method of Scaling Ships'	December	168	Jet-impingement Apparatus for Assessing	December	160
Hydraulic Drive for Trawl Winches... ..	October	133	Corrosion	March	32
Hydraulic Fatigue Testing of Boiler Drums	January	11	Jets and Inlets in Ventilation	November	155
Hydraulic Servo Injector Pump	April	55	John Brown Gas Turbine Tests	January	6
Hydraulic Servo-Mechanisms. Compressi-	November	142	Joining of Aluminium Alloys	October	140
bility Effect in	October	137	Joints. Explosion Testing of Welded	August	112
Hydraulic Starter	September	125	Joints. Fatigue Strength of	September	113
Hydrodynamic Transmission for Marine	December	162	Joints. Gaskets and Bolted	August	108
Deck Machinery	July	99	Journal Bearings. Oil Holes in	June	76
I Beam. Combined Bending and Torsion of	November	155	Lakes Ore Carrier. Boilers for Large Great	November	142
Ice-breaker. Large Finnish	October	137	<i>La Marseillaise</i> . French Passenger Motor-	March	43
Icebreakers. Kort Nozzles for	September	125	ship	July	90
Ice-Breakers. "Wind" Class	September	126	Laminar Flow. Hull Design for	January	7
Ice-breaking Ferry for State of Michigan ...	December	162	Large American Diesel Engines	January	3
I.C. Engines. Exhaust Process in Four-	July	99	Large Diesel Engine for Tankers	October	135
stroke	November	155	Large Finnish Ice-breaker	November	142
Impact of a Body on a Water Surface	May	67	Large French River Tug	March	43
Impregnated Dry Lubrication Process	July	85	Large Molasses Tankers	July	90
Improvements in Mooring Anchors	July	92	Large Motor Tanker	January	7
Indicator. Balanced-pressure Engine	December	161	Large Reversion Reduction Gear	January	3
Indicator. Combustion and Compression	November	145	Largest Crossley-engined Ship	October	135
Pressure	December	165	Largest Tanker. World's	November	142
Individual Heating, Cooling and Ventilating	March	38	Launching Lubricant. New... ..	September	124
Unit			Laundering. Sea Water	March	35

	Issue	Page		Issue	Page
Leak Detector. Portable	March	33	Merchant Ship Propulsion. Geared Steam	May	62
Leak Detector. Refrigerant	March	33	Turbines for	August	105
Lengthening Valve Life	July	88	Mercury Shaft Seal	September	127
Lifeboat. Self-bailing Self-righting ...	March	41	Metal Spraying of High-temperature Metals	October	134
Light Alloy Pistons of Spanish Manufacture	September	121	and Alloys	September	127
Light Weight Steam Propulsion Plant.			Metal Transfer from Piston Rings to		
Novel	November	149	Cylinders		
Light Weight Welded Structures	January	7	Metals and Alloys. Metal Spraying of High-	September	127
Lighthouse and Buoy Tender. New			temperature	March	43
Canadian	July	91	Metals at High Temperature... ..	January	9
Lightship. Experimental Robot	July	90	Metallizing of Packing Areas	May	71
Liner. Japanese-built 17-knot	June	80	Metallurgy—Peening of Welds. Welding ...	April	55
Liner Wear. Theory of Cylinder	February	25	Meter. Marine Shaft Horse-power-hour ...	December	157
Liners. Electrical Power Plant of New			Mezzo-deck Grain Division	September	126
American President	August	110	Michigan. Ice-breaking Ferry for State of	March	41
Liners. Water Side Deterioration of Diesel			Michigan Tank. Modernization of the ...	December	159
Engine Cylinder	September	120	Mild Steel. Ductility of Arc Welds in ...	January	9
Liquid Cooling of Centrifugal Compressors.			Mild Steel Plates. Notch Sensitivity of ...		
Internal	November	141	Mild Steel Prior to Fabrication. Surface	March	33
Load Capacity of Lubricants	August	112	Preparation of	May	57
Localized Formation of Magnetic Iron Oxide			Mirrlees Diesel Engine. New	December	162
in Boilers	September	123	Mixture of Water and Steam. Flow of	May	68
Locked-in Stresses in Welded Box Girder ...	November	156	Flashing	May	69
Longitudinal Vibrations of Marine Propul-			Model Anchors. Investigations on	November	151
sion-shafting Systems	January	16	Model Date. Review of Ship	November	152
Lost Wax Process of Precision Casting ...	March	39	Model Resistance Data. New	August	104
Lubricant. "Molykote", a New	July	100	Model Testing. Ship	May	66
Lubricant. New Launching	September	124	Model Tests. Full-scale Check on	December	166
Loop Scavenging. Test Apparatus for			Model Tests on Single-step Planing Surfaces		
Studying	February	24	Models of Cargo Vessels. Systematic Tests	April	55
Low Carbon, Low Alloy Steel Containing	March	40	with	May	67
Boron. Strength of	February	20	Models of Fast Cargo Vessels. Further Tests	August	103
Lubricants for Steam Engines	July	87	with	April	48
Lubricants. Load Capacity of	August	112	Models of High Speed Ships. Experiments	March	41
Lubricants. Storage Additive Type	March	36	with	December	161
Lubricating Oils. Kinetic Boundary Friction			Modern Marine Gears	June	76
of	January	9	Modern Tanker Construction	July	90
Lubricating Oils. Performance of Crankcase	March	39	Modernization of the Michigan Tank ...	February	21
Lubricating Problems. Shipboard	March	31	Moisture Control. Gear Case	July	94
Lubrication. Dry Film	May	69	Moisture Separator	July	100
Lubrication of Ball and Roller Bearings ...	July	91	Molasses Tankers. Large	June	82
Lubrication Oil Failure on Geared-turbine			Molten Metal Welding	May	67
Ship	January	11	Molybdenum, Titanium and Zirconium.	June	74
Lubrication Process. Impregnated Dry ...	November	155	New Metals—	August	112
Lumber Carrier. New Packaged	November	152	"Molykote", a New Lubricant	January	8
Machinery for Two Holt Ships. 8,000 s.h.p.			Monel Metal to Steel. Seam Welding ...	May	65
Propelling	July	87	Mooring Anchors. Improvements in ...	December	163
Machining of Heated Metals... ..	August	103	Motor Sealer <i>Norsel</i>	December	166
Macro-roughness on Performance of Parallel			Motorship. Danish Cross-Channel	October	140
Thrust Bearings. Effect of	June	82	Motorship. Diesel-electric	February	27
Magnetic Iron Oxide in Boilers. Localized			Motorship. Fast Argentine	August	108
Formation of	September	123	Motorship for Red Sea Service	January	7
Mail Service. Considerations in Provision and			Motorship for the Argentine. Italian ...	November	151
Operation of Overseas	March	37	Motorship <i>La Marseillaise</i> . French Passenger	October	138
Malta. <i>Breconshire</i> Raised off	November	157	Motorship <i>Trudvang</i> . Norwegian	February	18
Manœuvring Characteristics Improved by			Motor Ships. Boiler Oil in American ...	November	142
Reversing Propeller Rotation	February	18	Motor Tanker. Large	October	133
Marine Gas-turbine Research	August	102	Motor Train Ferry. First English Channel	May	65
Marine Oil Burner	September	122	Motor Vessel <i>Rupertsland</i>	August	109
Marine Pumps. Self-priming	June	75	Motor Vessels. Canadian-built		
Marine Reversing Gear	February	23	Motor Vessels on Heavy Fuel. Running ...		
Marine Shaft Horse-power-hour Meter ...	April	55	Multi-cylinder Diesel Engine. Hexagonal ...		
Masts. Welded Aluminium Tripod	July	91	Multi-engine Propelled French Cargo Boats		
Masts with Heavy Derricks. Tests on Stayed			Multiplex Engine. First		
Measured Wave Making of Hull Forms.			Naval Ships. Propelling Machinery for ...	August	105
Calculated v.	December	167	Naval Shipyards. Arc Welding in Spanish	May	70
Measurement of Torque. Electrical	January	11	Negative Spring	February	19
Measuring Elongation of Pre-stressed Parts			Nested-type Reduction Gears	December	161
Mechanical Engineering in Atomic Energy	July	92	New Air Distributor for Oil Burner ...	December	162
Mechanical Vacuum Pumps	July	92	New Arctic Patrol Vessel	February	28
	May	59	New Canadian Lighthouse and Buoy Tender	July	91

	Issue	Page		Issue	Page
New Cargo Vessel	January	8	Overseas Mail Service. Considerations in Provision and Operation of	March	37
New Coastwise Passenger Service	August	111	Oxide in Boilers. Localized Formation of Magnetic Iron	September	123
New Corrosion Test	December	161	Oxygen Cutting of Stainless Steel	February	21
New Cunard Cargo Liner	November	152	Oxy-kinetic Flame Cutting Process	August	101
New Diesel-electric Tug	November	151	Packaged Lumber Carrier. New	November	152
New Etching Process	January	9	Packing Areas. Metallizing of	January	9
New Forms for Ships' Sterns	May	66	Paddle Steamer for River Ganges	July	93
New French Cable Ship	September	128	Paint Coatings in Sea Water. Electro-chemical Study of	April	55
New Gas Turbine Plant	September	115	Paints. Anti-fouling	June	74
New German Cargo Vessels	February	17	Paints. Cementiferous	June	74
New Hidden Arc Welding Process	November	156	Paints. Exposure Trials of Weatherwork	February	23
New Launching Lubricant	September	124	Painting Tool. New	January	10
New Metals—Molybdenum, Titanium and Zirconium	July	94	Pametrada Progress	January	90
New Mirrless Diesel Engine	May	57	Passenger and Cargo Liner <i>Helenus</i>	March	30
New Model Resistance Data	November	151	Passenger Motorship <i>La Marseillaise</i> . French Passenger Service. New Coastwise	October	140
New Ore Carriers	September	124	Passenger Service. New Coastwise	August	111
New Packaged Lumber Carrier	November	152	Passenger Ships. Design of Hotel Services for	March	31
New Painting Tool	January	10	Passenger Vessel <i>Balmoral</i> . Twin-screw	February	28
New Propeller Dynamometer	March	41	Patrol Vessel. New Arctic	February	28
New Reliner for Diesel Bearings	April	53	Peening of Welds. Welding Metallurgy—Percussion Welding—Aluminium	May	71
New Rudder Design	March	30	Percussion Welding—Aluminium	March	33
New Suction Dredger... ..	December	159	Percussion Welding Developments	June	80
New Swedish Oil Engine	March	36	Percussion Welding—Iron and Steel	March	32
New Tanker <i>Atlantic Engineer</i>	December	165	Performance of Anti-corrosive Compositions in Sea Water	September	117
New York Ferryboats... ..	September	125	Performance of Crankcase Lubricating Oils	March	39
<i>Norsel</i> . Motor Sealer... ..	June	74	Photocell Smokemeter	February	25
Norwegian Motorship <i>Trudvang</i>	February	27	Photo-elastic Laboratory	June	83
Norwegian Tramp Vessels	June	78	Photo-elastic Methods to Ship Design Problems. Application of	January	9
Norwegian Vessel. German Diesel for Notch Bend Test. High Frequency	August	107	Photo-electric Crankcase Oil Tester	November	154
Notch Sensitivity of Mild Steel Plates	June	82	Pilot Fuel Injection System	August	108
Notch-tensile Tests. Transition Temperature of Ship Plate in	January	9	Pipe-line System. Tanker	November	151
Novel Light Weight Steam Propulsion Plant	July	91	Pipes. Research on Exhaust	September	121
Nozzles for Icebreakers. Kort	November	149	Piping Caused by Gas Pressure Pulsations. Vibration of	March	42
Oerlikon Radial Gas Turbine	October	137	Piping. Corrosion of Copper Circulating Piping. Thermal Shock Tests of Austenitic and Ferritic Steam	July	99
Off-design Performance of Turbo-compressor Stage	November	145	Piston Diesel Engine. Seven-cylinder Opposed	July	88
Oil and Pulverized Coal. Residual	March	32	Piston Gasifier and Turbine. Free	January	12
Oil Ash. Corrosion of Heat Resisting Steels by Vanadium Containing	May	58	Piston Ring Wear. Combating	January	15
Oil Burner. Marine	September	117	Piston Rings. Carbon	November	154
Oil Burner. New Air Distributor for	September	122	Piston Rings. Chromium-plated	March	40
Oil Can Control Wear	December	162	Pistons of Spanish Manufacture. Light Alloy	September	121
Oil. Combustion of Gas	June	81	Piston Rings to Cylinders. Metal Transfer from	October	134
Oil Engine. New Swedish	November	143	Pitch Propeller in Collier. Controllable	August	107
Oil Engine Progress	March	36	Pitch Ratio. Variation of Propeller Efficiency with	August	106
Oil Failure on Geared-turbine Ship. Lubrication	October	134	Planetary Gears. Efficiency of	November	155
Oil-fired Boiler. Composite Waste-heat and Oil-fired Marine Boilers	January	11	Planing Surfaces. Model Tests on Single-Step	May	66
Oil Holes in Journal Bearings	January	5	Plastic Coated Tug for the Amazon	February	28
Oil in American Motor Ships. Boiler	August	109	Plate in Notch-tensile Tests. Transition Temperature of Ship	July	91
Oil Stripping Pumps. Cargo	November	155	Plates. Notch Sensitivity of Mild Steel	January	9
Oil Tanker Progress	August	108	Polar Diesel-engined Ship. First Gray	May	63
Oil Tester. Photo-electric Crankcase	April	52	Portable Leak Detector	March	33
Oils. Performance of Crankcase Lubricating Oily Water Separators. Alarm Device for	March	31	Powder Coupling	June	81
Opposed-piston Two-stroke Oil Engine	November	154	Power Cutting of Stainless Steel	July	95
Optical Method Supersedes Templates	March	39	Power Plant Possibilities. Future	December	166
Optimum Screw Propulsion for Self-propelled Barges	April	45	Practical Ship Dehumidification	January	9
Ore Carrier. Boilers for Large Great Lakes Ore Carriers. New	January	15	Precautions when a Turbine is Idle in Port	January	11
<i>Oslofjord</i> . Double-acting Two-stroke Engines of Passenger Liner	December	163	Precision Casting. Lost Wax Process of	March	39
Outlook for Ceramics in Gas Turbines	July	99			
Overlaying with Aluminium-bronze Electrodes	January	6			
Overloading of Propulsion Reduction Gear	September	124			

	Issue	Page		Issue	Page
Pressure Drop in Vortex Dust Collectors.			Radial Gas Turbine. Oerlikon	November	145
Reduction of	June	81	Radiation. International Research on Flame	August	103
Pressure Indicator. Combustion and Com-			Radiography. Hot	December	160
pression	July	92	Radiography of Welds in Ship Construc-		
Pressure Pulsations. Vibration of Piping			tion	February	21
Caused by Gas	March	42	<i>Randfonn</i> . Diesel-engined Tanker	October	140
Pressure Vessels. Pulsation Testing of ...	December	167	Ratio. Variation of Propeller Efficiency with		
Pressure Vessels. Welded	December	159	Pitch	August	106
Pressure Welding of Boiler Tubes	February	20	Reciprocators for Ships. High-speed Steam	February	23
Processing Plant. Fishing Vessel with			Reciprocators. High Speed	September	119
Fish	October	140	Recorders. Comparative Tests on CO ₂ ...	October	136
Progress in High Duty and Alloy Cast			Red Sea Service. Motorship for	December	163
Iron	March	37	Reduction Gear. Large Reversion	January	3
Producer-gas-driven Towboat. Twin Screw	February	24	Reduction Gear. Overloading of Propul-		
Production of Gas Turbine Blades	September	115	sion	July	86
Propelled French Cargo Boats. Multi-			Reduction Gear Unit. Controllable Propeller		
engine	May	65	System and	January	2
Propeller. Coastal Passenger Ships with			Reduction Gears. Nested-type	December	161
Variable Pitch	February	18	Reduction of Pressure Drop in Vortex Dust		
Propeller Dynamometer. New	March	41	Collectors	June	81
Propeller Efficiency with Pitch Ratio. Varia-			Refractories. Flue Dust Blower Uses ...	April	55
tion of	August	106	Refrigerant Leak Detector	March	33
Propeller Guards	August	105	Refrigerated Cargo Vessel <i>Baltrover</i> ...	December	164
Propeller in Collier. Controllable Pitch ...	August	107	Refrigeration and Air Conditioning		
Propeller Rotation. Manœuvring Charac-			Machinery in H.M. Ships	January	10
teristics Improved by Reversing	February	18	Regulating Device. Electric Propulsion ...	November	148
Propeller. Schnitger	September	119	Relative Corrosion Behaviour of Different		
Propeller Shafts. Corrosion of	August	104	Sea-water	June	73
Propeller System and Reduction Gear Unit.			Relative Ductility in Welding Ship-plate ...	May	72
Controllable	January	2	Reliner for Diesel Bearings. New	April	53
Propeller. Torsional Vibrations Caused by	August	107	Repair of Iron Castings	March	32
Propellers. Cavitation on Screw	November	146	Research. Accelerated Cavitation	September	128
Propellers. Design of	April	53	Research Association. First Six Years of		
Propellers. Dutch Ferries with Variable-			British Shipbuilding	September	124
pitch	November	148	Research. Diesel Engine	December	162
Propellers. Five-bladed	November	147	Research. Marine Gas-turbine	August	102
Propellers for Scheldt Ferries. Reversible ...	June	79	Research on Exhaust Pipes	September	121
Propellers. Full-scale Trials of Schnitger ...	August	104	Research on Flame Radiation. International	August	103
Propelling Machinery for Naval Ships	August	105	Research Vessel <i>Africana II</i> . Fisheries ...	May	67
Propelling Machinery for Two Holt Ships.			Residual Oil and Pulverized Coal	May	58
8,000 s.h.p.	July	87	Residual Stresses in Welded Tanker During		
Propelling Units. "Harbormaster"	October	135	Construction	December	167
Properties of Gas-turbine Fuels	January	8	Resin Coating for Metal	March	42
Properties of Gas Turbine Rotor Disk	February	22	Resistance Data. New Model	November	151
Properties of Thin Walled Curved Tubes of			Resistance-type Strain Gauges	August	112
Short-bend Radius	August	103	Reversible Propellers for Scheldt Ferries ...	June	79
Protection. Cargo	November	141	Reversible Transmission for Gas Turbines...	March	34
Protection for Ships' Hulls. Vinyl	December	164	Reversing Gear. Marine	February	23
Protection of Ship in Sea Water. Cathodic	October	132	Reversing Propeller Rotation. Manœuvring		
Propulsion. Atomic Power and Ship	April	50	Characteristics Improved by	February	18
Propulsion. Cycloidal	January	1	Reversion Reduction Gear. Large	January	3
Propulsion-shafting Systems. Longitudinal			Review of Ship Model Data	May	69
Vibrations of Marine	January	16	Rhine Tug. Quadruple-screw	February	17
Pulsating Air Intake for Free-Piston Gasi-			Ricardo Engine with Air Charging Cylinder	April	45
fiers	August	102	Ring Prevents Smashed Fingers. Safety ...	October	131
Pulsation Testing of Pressure Vessels ...	December	167	River Barges. Structural Strength of ...	September	125
Pulsations. Vibration of Piping Caused by			River Ganges. Paddle Steamer for	July	93
Gas Pressure	March	42	River Tug. Large French	March	43
Pulverised Coal. Residual Oil and	May	58	Rivet Slip, Stress Distribution, and the		
Pump. Bilge	May	61	Deflection of Ships' Hulls	February	19
Pump Evaporator. Diesel Driven Heat	March	43	Robot Lightship. Experimental	July	90
Pump. Flow Conditions in Centrifugal ...	December	165	Roll. Stabilization Reduces Ship's	March	37
Pump. Hydraulic Servo Injector	January	4	Roller Bearings. Lubrication of Ball and ...	July	91
Pumps. Cargo Oil Stripping	April	52	Roller Chain Drives	March	41
Pumps for Marine Service. Boiler Feed ...	March	35	Rolling Wing Decks	December	164
Pumps. Mechanical Vacuum	May	59	Rotating Cup Type Atomizers	January	8
Pumps. Self-priming Marine	June	75	Rotor Disk. Properties of Gas Turbine ...	February	22
Pumps Without Stuffing Boxes	November	154	Rotor Shaft. Straightening Turbine ...	November	143
Pyrometer. Diesel Exhaust	January	5	Round Doors	November	150
Quarter-wheelers for West Africa	October	138	Round the World Ships	January	6
Quadruple-screw Rhine Tug... ..	February	17	Rudder Design. New	March	30
			Rudder of Novel Design for Tanker ...	April	46

	Issue	Page		Issue	Page
Rudder, Trim and Stern Wave. Dependence of Wake on Shape of	April	56	Ships' Hatch Covers	June	78
Running Motor Vessels on Heavy Fuel ...	November	142	Shipbuilding in Australia	September	125
Rupertsland. Motor Vessel	October	138	Shipbuilding in the U.S.A.	July	89
Ruston Gas Turbine	March	44	Shipbuilding Research Association. First Six Years of British	September	124
Safety Precautions. Diesel Engine Crankcase	April	53	Ship-plate. Relative Ductility in Welding... ..	May	72
Safety Ring Prevents Smashed Fingers ...	October	131	Ship-repairing in South Africa	April	50
Safety Valve. Sealing of High-pressure Steam	July	99	Shock Test of High Temperature Alloys. Thermal	December	168
Sampling. Automatic De-gasser for Steam Scale Effect Experiments on Twin Screw Hull Tests	April	55	Shock Tests of Austenitic and Ferritic Steam Piping. Thermal	July	99
Scaling Ships' Hulls. Water-blast Method of Scavenging. Test Apparatus for Studying Loop	June	79	Short-bend Radius. Properties of Thin Walled Curved Tubes of	August	103
Scheldt Ferries. Reversible Propellers for ...	February	24	Shrinkage Distortion in Welding	October	129
Schneider Pusher Unit for Dumb Barges. Voith	March	40	Significant Factors in Economic Handling of Cargo	December	163
Schnitger Propeller	June	79	Single-casing Turbines for Cross-Channel Ship	October	139
Schnitger Propellers. Full-scale Trials of ...	August	111	Single-cylinder Turbine for Great Lakes Bulk Carrier	November	146
Screw Propellers. Cavitation on	September	119	Single Gear Tooth Bending Fatigue Test ...	May	57
Screw Propulsion for Self-propelled Barges. Optimum	August	104	Single-step Planing Surfaces. Model Test on Size on Design and Performance of Internal-combustion Engines. Effect of	May	66
Seagoing Hopper Dredge <i>Essayons</i>	November	146	Small Geared Diesel Ship	October	134
Seakindly Ships. Design of	July	99	Smaller Vessels. Doxford Engine for	March	42
Sea Water. Cathodic Protection of Ship in Sea-water Cooling Systems. Corrosion Problems in	February	22	Smoke Abatement. Funnel Design and ...	January	13
Sea Water. Electro-chemical Study of Paint Coatings in	September	114	Smokemeter. Photocell	July	90
Sea Water. Performance of Anti-corrosive Compositions in	October	132	Soldering. Ultrasonic	February	25
Sea Water upon Cavitation Tests. Effect of Gas Content of	October	132	South Africa. Ship-repairing in	April	47
Sea-waters. Relative Corrosion Behaviour of Different	April	55	Soviet Union. Electric Welding and Cutting Under Water in the	April	50
Seal. Mercury Shaft	March	35	Spanish-built Sulzer Engine. First... ..	June	83
Sealer <i>Norsel</i> . Motor	September	117	Spanish Manufacture. Light Alloy Pistons of	January	5
Sealing of High-pressure Steam Safety Valve	September	119	Spanish Naval Shipyards. Arc Welding in Speed of Rise of Air Bubbles in Liquids ...	September	121
Seam Welding Monel Metal to Steel	September	119	Sprays. Bibliograph on	May	70
Self-bailing Self-righting Lifeboat	June	73	Spraying of High-temperature Metals and Alloys. Metal	July	99
Self-priming Marine Pumps... ..	August	105	Spring. Negative	February	24
Self-Starter. Gas Turbine	June	74	Stabilization Reduces Ship's Roll	September	127
Self-unloading Ships	July	99	Stabilizing Gear in the <i>Chusan</i>	February	19
Separator. Moisture	August	105	Stainless Steel. Friction Band-sawing of ...	March	37
Separators. Alarm Device for Oily Water ...	June	74	Stainless Steel. Oxygen Cutting of	September	114
Servo Injector Pump. Hydraulic	July	99	Stainless Steel. Power Cutting of	February	22
Servo-Mechanisms. Compressibility Effect in Hydraulic	June	82	Stainless Steel. Threading of	February	21
Seven-cylinder Opposed Piston Diesel Engine Shaft Horse-power-hour Meter. Marine ...	March	41	Stainless Steel. Hydraulic	July	95
Shaft Seal. Mercury	June	75	Starting of High Speed Diesels. Cold	March	39
Shaft. Straightening Turbine Rotor	May	58	Stayed Masts with Heavy Derricks. Tests on Steam, by Aluminium. Treatment of Burns Due to	October	133
Shaft with Keyways. Torsion of	September	125	Steam Atomizing Burners	October	136
Shafts. Corrosion of Propeller	June	76	Steam Cycle at 1,600 deg. F.	June	80
Shafting. Vibrations of Marine	April	45	Steam Engine. Geared	June	74
Shallow-draft Tanker. Twin-screw	January	4	Steam Power. Application of Gas Turbine Technique to	March	37
Shells of Marine Boilers. Cooling Effect of Tube Holes in Thick	December	168	Steam Trawler <i>Andanes</i>	March	41
Shifting Boards for Ballasted Cargo Vessels Shielded Stud Welding of Aluminium Alloys Shipboard Lubricating Problems	July	88	Steel. Aluminium Coated	May	64
Ship-model Tests. Circulating Water Channel for	April	55	Steel Containing Boron. Strength of Low Carbon, Low Alloy	September	117
Ship Model Testing	August	105	Steel. Ductility of Arc Welds in Mild	December	160
Ship's Funnel	November	153	Steel. Friction Band-sawing of Stainless ...	May	71
			Steel in Estuarine Tropical Waters. Corrosion of	February	22
			Steel in Sea Water. Corrosion of Iron and Steel Member. Buckling of Compressed ...	September	117
			Steel. Oxygen Cutting of Stainless	December	160
			Steel. Percussion Welding—Iron and	May	71
			Steel Plates. Notch Sensitivity of Mild ...	February	21
			Steel. Power Cutting of Stainless	March	32
				January	9
				July	95

	Issue	Page		Issue	Page
Steel Prior to Fabrication. Surface Preparation of Mild	March	33	Tank Activities. Stevens Towing	November	153
Steel Protection by Chromium Diffusion ...	October	131	Tank. Explosion of Empty Diesel-oil Fuel	December	159
Steel. Seam Welding Monel Metal to ...	June	82	Tank. Modernization of the Michigan ...	March	41
Steel Sheet. Hot-dipped Aluminium Coatings on	December	160	Tank. Swedish Cavitation	October	137
Steel. Threading of Stainless	March	39	Tank Vessels. Cargo Distribution in ...	March	31
Steels by Vanadium Containing Oil Ash. Corrosion of Heat Resisting	September	117	Tanks. Australia's Towing	July	89
Steering Control. Automatic	November	147	Tanks. Electrolytic Descaling of	July	95
Steering Gear. Unusual	November	147	Tanker. A 20-knot 24,000 b.h.p.	November	152
Stern Wave. Dependence of Wake on Shape of Rudder, Trim and	April	56	Tanker <i>Atlantic Engineer</i> . New	December	165
Sterns. New Forms for Ships'	May	66	Tanker. British Built Swedish Steam ...	July	89
Stevens Towing Tank Activities	November	153	Tanker Construction. Modern	April	48
Storage Additive Type Lubricants	March	36	Tanker During Construction. Residual Stresses in Welded	December	167
Storage of Boilers. Dry and Wet	May	58	Tanker. Large Motor	January	7
Straightening Turbine Rotor Shaft	November	143	Tanker Members. Stresses in	May	72
Strain Gauge Tests on Epicyclic Gears ...	April	51	Tanker Progress. Oil... ..	March	31
Strain Gauges. Resistance-type	August	112	Tanker Pipe-line System	November	151
Strength of Decks of Ships	June	80	Tanker <i>Randfjonn</i> . Diesel-engined	October	140
Strength of Joints. Fatigue	December	160	Tanker. Rudder of Novel Design for ...	April	46
Strength of Low Carbon, Low Alloy Steel Containing Boron	February	20	Tanker. Twin-screw Shallow-draft... ..	January	8
Strength of River Barges. Structural ...	September	125	Tanker <i>Velutina</i>	October	139
Stress Corrosion Tests	March	42	Tanker with Special Reference to Machinery. Design of Modern	August	104
Stress Distribution, and the Deflection of Ships' Hulls. Rivet Slip	February	19	Tanker. World's Largest	November	142
Stress Relief by Heat Treatment of Cast Iron	November	143	Tankers. Design of a Class of 28,000-ton	February	28
Stress upon Corrosion. Influence of ...	November	145	Tankers. Large Diesel Engine for	June	76
Stresses at High Speed. Gear-tooth	May	69	Tankers. Large Molasses	July	90
Stresses. Circular Cylinder	May	69	Temperature Differences. Galvanic Corrosion of Iron Due to	September	116
Stresses. Initial Bolt	December	165	Temperature. Effect of Fatigue on Transition	May	72
Stresses in Tanker Members	May	72	Temperature Measurements in High Velocity Gas Streams	April	49
Stresses in Welded Box Girder. Locked-in	November	156	Temperature of Ship Plate in Notch-tensile Tests. Transition	July	91
Stresses in Welded Tanker During Construction. Residual	December	167	Templates. Optical Method Supersedes ...	December	163
Structural Failures of Ships	April	52	Tender <i>Aestus</i> . Survey	March	30
Structural Steel. Flame Straightening and Forming	March	32	Tender. New Canadian Lighthouse and Buoy	July	91
Structural Strength of River Barges ...	September	125	Test Apparatus for Studying Loop Scavenging	February	24
Stud Welding	February	19		March	40
Stud Welding of Aluminium Alloys. Shielded	April	54	Tester. Photo-electric Crankcase Oil ...	November	154
Studies on Marine Fouling Organisms ...	September	117	Testing Cargo Booms... ..	February	28
Stuffing Boxes. Pumps Without	November	154	Testing. Diesel Fuel	November	154
Suction Cutter Dredger for France. Dutch	August	111	Testing of Boilers	May	66
Suction Dredger. New	December	159	Testing Resistance to Cavitation Erosion ...	May	69
Sulphur-containing Exhaust Gases of Internal Combustion Engines	December	165	Tests for Underwater Anti-corrosive Compositions	February	24
Sulphur Content of Diesel Fuels	October	136	Tests of Standard Doxford Engine Using Heavy Fuel	February	24
Sulzer Engine. First Spanish-built ...	January	5	Tests on Stayed Masts with Heavy Derricks	June	80
Superheat Control	February	27	Theory of Cylinder Liner Wear	February	25
Superheater. Water Tube Boiler and Steam Superstructure and Main Hull Girder. Interaction between	February	18	Theory of Valves for Compressors	December	168
Supertanker. American	January	12	Thermal Expansion Effects in Composite Ships	May	68
Supertankers. 27,000-ton	May	68	Thermal Insulation	December	161
Supertankers. Bethlehem	August	110	Thermal Insulation for Marine Gas Turbine Plant. Ventilated	March	43
Surface Preparation of Mild Steel Prior to Fabrication	March	33	Thermal Shock Test of High Temperature Alloys	December	168
Surfaces. Examination of	March	42	Thermal Shock Tests of Austenitic and Ferritic Steam Piping	July	99
Survey Tender <i>Aestus</i>	March	30	Thin Walled Curved Tubes of Short-bend Radius. Properties of	August	103
Swedish Cavitation Tank	October	137	Threading of Stainless Steel	March	39
Swedish Oil Engine. New	March	36	Three-drum Water-tube Boilers. Yarrow ...	September	122
Swedish Steam Tanker. British Built	July	89	Timbers for Marine Use	June	84
Systematic Geometrical Variation of Ship Forms	August	104	Titanium and Zirconium. New Metals—Molybdenum,	July	94
Systematic Tests with Models of Cargo Vessels	December	166	Titanium as High-strength Light-weight Material	February	20

	Issue	Page		Issue	Page
To Keep Chain Locker Dry	October	133	Turbine Plant. Torsional Vibrations in Geared	July	88
Tools. Isotopes as Engineering	February	25	Turbine Plant. Ventilated Thermal Insulation for Marine Gas	March	43
Tooth Bending Fatigue Test. Single Gear Torque. Electrical Measurement of... ..	May	57	Turbine Practice. American Gas	September	116
Torsion of I Beam. Combined Bending and Torsion of Shaft with Keyways	April	55	Turbine Progress in France. Gas	November	144
Torsional Vibrations	November	143	Turbine Rotor Disk. Properties of Gas	February	22
Torsional Vibrations Caused by Propeller	July	93	Turbine Rotor Shaft. Straightening	November	143
Torsional Vibrations in Geared Turbine Plant	August	107	Turbine. Ruston Gas	March	44
Towboat. Twin Screw Producer-gas-driven	July	88	Turbine Self-Starter. Gas	May	58
Towing Tank Activities. Stevens	February	24	Turbine Ship's Propulsion Plant. Hot Air	March	34
Towing Tanks. Australia's	November	153	Turbine Steamship <i>Clan Shaw</i>	June	75
Tracing Defects in Diesel Engines	July	89	Turbine Technique to Steam Power. Application of Gas	April	50
Tractor. Cathodic Protection of	January	12	Turbine Tests. John Brown Gas	July	97
Train Ferry. First English Channel Motor	March	40	Turbine Using Two Types of Machine. Gas	July	85
Tramp Vessels. Norwegian	November	151	Turbines. Cleaning Steam	January	3
Transient Flow of Gases	June	78	Turbines. Combustion Chambers for Marine Gas	February	22
Transition Temperature. Effect of Fatigue on	March	35	Turbines for Cross-Channel Ship. Single-casing	October	139
Transition Temperature of Ship Plate in Notch-tensile Tests	May	72	Turbines for Merchant Ship Propulsion. Geared Steam	May	62
Transmission for Gas Turbines. Reversible Transmission for Marine Deck Machinery. Hydrodynamic	July	91	Turbines. Heat Exchanger System for Gas	February	22
Trawl Winches. Hydraulic Drive for	January	11	Turbines in Dutch Vessels. American	November	146
Trawler <i>Andanes</i> . Steam	May	61	Turbines. Japanese Gas	September	115
Trawler Boiler Plant. Economizer for	June	80	Turbines. Outlook for Ceramics in Gas	April	56
Treatment of Burns Due to Steam, by Aluminium	October	136	Turbines. Reversible Transmission for Gas Turbo-compressor Stage. Off-design Performance of	March	32
Trials of Schnitger Propellers. Full-scale	June	74	Turbo-electric Machinery of the <i>Kairouan</i>	September	118
Trim and Stern Wave. Dependence of Wake on Shape of Rudder	August	104	Turbo-generators. Auxiliary	February	23
Tripod Masts. Welded Aluminium	April	56	Turning Vanes at Sharp Elbows. Use of	November	154
Tropical Waters. Corrosion of Steel in Estuarine	July	91	Twin Screw Hull Tests. Scale Effect Experiments on	April	55
<i>Trudvang</i> . Norwegian Motorship	September	117	Twin-screw Passenger Vessel <i>Balmoral</i>	February	28
Tube Banks. Heat Transfer and Fluid Friction in Viscous Flow Across	February	27	Twin Screw Producer-gas-driven Towboat	February	24
Tube Holes in Thick Shells of Marine Boilers. Cooling Effect of	March	35	Twin-screw Shallow-draft Tanker	January	8
Tubes. Friction and Heat Transfer in	April	55	Two-stage Injection	August	109
Tubes of Short-bend Radius. Properties of Thin Walled Curved	December	163	Two-stroke Engine Installation. Double-acting	March	42
Tubes. Pressure Welding of Boiler	April	55	Two-stroke Engines of Passenger Liner <i>Oslofjord</i> . Double-acting	February	25
Tug Design	August	103	Two-stroke Oil Engine. Opposed-piston	January	15
Tug for the Amazon. Plastic Coated	February	20	Ultrasonic Flaw Detector	December	161
Tug. Large French River	December	164	Ultrasonic Soldering	April	47
Tug. New Diesel-electric	February	28	Ultrasonic Vibrations as Possible Source of Fires and Explosions	September	116
Tug. Quadruple-screw Rhine	March	43	<i>Ulysses</i> . Geared Turbine Cargo Liner	January	7
Turbine at Admiralty Laboratory. Gas	November	151	Underwater Anti-corrosive Compositions. Tests for	February	24
Turbine Blades. Production of Gas	February	17	Underwater Welding. Arc	March	38
Turbine Blading. Vibration of Marine	July	97	Unusual Steering Gear	November	147
Turbine Booster Propulsion Plant. Gas	September	115	United Kingdom—Great Lakes Steamships	January	6
Turbine Cargo Liner <i>Ulysses</i> . Geared	May	57	Upside Down. Ferry Boats Built	September	124
Turbine. Combined Gas and Steam	July	96	U.S.A. Shipbuilding in the	July	89
Turbine Combustion Chamber Air Supply. Gas	January	7	Use of Turning Vanes at Sharp Elbows	November	154
Turbine. Danish Marine Gas	November	145	Vacuum Pumps. Mechanical	May	59
Turbine Design. World Progress in Gas	October	131	Valve Life. Lengthening	July	88
Turbine. Experimental Closed-cycle Gas	January	3	Valve Motor. Gate	March	31
Turbine for Great Lakes Bulk Carrier. Single-cylinder	June	73	Valve. Sealing of High-pressure Steam Safety	July	99
Turbine. Free Piston Gasifier and	May	59	Valves for Compressors. Theory of	December	168
Turbine. French Naval Gas	November	146	Vanadium Containing Oil Ash. Corrosion of Heat Resisting Steels by	September	117
Turbine Installation. Gas	January	12	Vanes at Sharp Elbows. Use of Turning	November	154
Turbine is Idle in Port. Precautions when a Turbine. Oerlikon Radial Gas	June	73	Variable Pitch Propeller. Coastal Passenger Ships with	February	18
Turbine Operation at 1,500 deg. F. Gas	May	60	Variable-pitch Propellers. Dutch Ferries with	November	148
Turbine Plant. Gas	January	10			
Turbine Plant. New Gas	September	115			

	Issue	Page		Issue	Page
Variation of Propeller Efficiency with Pitch Ratio	August	106	Wear. Oil Can Control	June	81
Variation of Ship Forms. Systematic Geometrical	August	104	Wear. Theory of Cylinder Liner	February	25
Velocity Gas Streams. Temperature Measurements in High	April	49	Weather Deck Coating System Sought	September	127
<i>Velutina</i> . Tanker	October	139	Weld Metal. Embrittlement of	December	160
Venezuela. Canadian-built Coasters for	June	79	Welds. Absorption of Gases by	June	83
Ventilated Thermal Insulation for Marine Gas Turbine Plant	March	43	Welds in Mild Steel. Ductility of Arc	December	159
Ventilating Systems. Application of Inlet Grilles to	November	143	Welds in Ship Construction. Radiography of	February	21
Ventilating Unit. Individual Heating, Cooling and	December	161	Welded Aluminium Tripod Masts	July	91
Ventilation. Jets and Inlets in	October	131	Welded Box Girder. Locked-in Stresses in	November	156
Ventilation of Ships' Holds	September	127	Welded Joints. Explosion Testing of	June	82
Vibration of Marine Turbine Blading	May	57	Welded Pressure Vessels	December	159
Vibration of Piping Caused by Gas Pressure Pulsations	March	42	Welded Ships. Effect of Buckles on Strength in	April	49
Vibrations as Possible Source of Fires and Explosions. Ultrasonic	September	116	Welded Structures. Light Weight	January	7
Vibrations Caused by Propeller. Torsional Vibrations in Geared Turbine Plant. Torsional	August	107	Welded Tanker During Construction. Residual Stresses in	December	167
Vibrations of Marine Propulsion-shafting Systems. Longitudinal	July	88	Welding—Aluminium. Percussion	March	33
Vibrations of Marine Shafting	January	16	Welding and Cutting Under Water in the Soviet Union. Electric	June	83
Vibrations. Torsional	December	161	Welding. Anticipated Distortion by	December	158
Vinyl Protection for Ships' Hulls	July	93	Welding. Arc Underwater	March	38
Viscosity Controller. Continuous	November	154	Welding Coated Materials. Brazing and	September	128
Viscous Flow Across Tube Banks. Heat Transfer and Fluid Friction in	March	35	Welding. Control of Distortion in Arc	July	93
Vitiated Atmospheres. Combustion in	May	72	Welding Developments. Percussion	June	80
Voith Schneider Pusher Unit for Dumb Barges	August	111	Welding High-nickel Alloys to Other Metals	April	54
Vortex Dust Collectors. Reduction of Pressure Drop in	June	81	Welding in Boilers	October	129
Wake on Shape of Rudder, Trim and Stern Wave. Dependence of	April	56	Welding in Spanish Naval Shipyards. Arc	May	70
Waste-heat and Oil-fired Boiler. Composite Water-blast Method of Scaling Ships' Hulls	January	5	Welding—Iron and Steel. Percussion	March	32
Water Separators. Alarm Device for Oily	June	79	Welding of Boiler Tubes. Pressure	February	20
Water Side Deterioration of Diesel Engine Cylinder Liners	April	45	Welding Metallurgy—Peening of Welds	May	71
Water Surface. Impact of a Body on a	September	120	Welding. Molten Metal	February	21
Water Tube Boilers and Steam Superheater	July	99	Welding Monel Metal to Steel. Seam	June	82
Watertube Boiler of the Double-flow Type	May	66	Welding of Aluminium Alloys. Shielded Stud	April	54
Water-tube Boilers. Yarrow Three-drum	January	15	Welding of Butt Welds. Arc	October	129
Wave Making of Hull Forms. Calculated v. Measured	September	122	Welding Process. Aircomatic	September	128
Wax Process of Precision Casting. Lost	December	167	Welding Process. New Hidden Arc	November	156
Wear. Combating Piston Ring	March	39	Welding Ship-plate. Relative Ductility in	May	72
	January	15	Welding. Shrinkage Distortion in	October	129
			Welding. Stud	February	19
			West Africa. Quarter-wheelers for	October	138
			Wet Storage of Boilers. Dry and	May	58
			Winches. Hydraulic Drive for Trawl	May	61
			"Wind" Class Ice-breakers	September	125
			Wing Decks. Rolling	December	164
			Work at Corrosion Testing Station	January	11
			World Progress in Gas Turbine Design	June	73
			World's Largest Tanker	November	142
			Yarrow Three-drum Water-tube Boilers	September	122
			Zirconium. New Metals—Molybdenum, Titanium and	July	94