

INDEX

Engineering Abstracts

	Issue	Page		Issue	Page
Acceleration of Ships...	June	83	Analysis of Ship Vibrations ...	January	16
Accelerator. Amyl Nitrate as Ignition ...	June	80	Analysis. Shortcomings of Structural ...	January	6
Accident. Steering Engine ...	January	14	Annual Meeting of American Bureau of Shipping ...	May	64
"Active Rudder". First Vessel with ...	September	119	Anodes. Magnesium ...	July	92
Additive to Relieve Boiler Slagging. Oil ...	October	139	Anti-corrosion Paints...	April	46
Additives. Gear-oil ...	January	6	Application of Ultrasonics to Metal Spraying	July	92
Adjustable Voltage Cargo Hoist ...	January	8	Arc Torch. Compressed Air...	May	71
Adjusting Gas Turbine Blade Clearance ...	October	133	Arc Welding. Argon...	May	70
Admiralty Range II Diesel Engine ...	June	82	Arc Welding of Low Chromium-molybdenum Steel Pipe...	November	145
Admiralty Standard Range I Engine ...	February	26	Arctic Service. Cargo Vessel for ...	July	95
Adsorbents. Air Drying by Granular ...	May	58	Argon Arc Welding ...	May	70
Advanced Steam Conditions. Steam Pipe Materials for ...	June	83	Asbestos Insulation. Sprayed ...	March	42
Advantages of Titanium ...	October	129	Atomic Engine ...	November	148
Aeronautical Engineer. Marine Gas Turbine from the Viewpoint of an ...	March	36	Atomic Ships ...	May	69
Air Arc Torch. Compressed...	May	71	Atomizers. Steam Oil ...	July	94
Air Compressor. Free Piston ...	November	153	Auricula in Service ...	June	78
Air Conditioned Troop Transport Vessel ...	September	126	Australian-built Doxford Engine. First ...	February	25
Air Drying by Granular Adsorbents...	May	58	Automatic Combustion Control for Marine Boilers ...	January	16
Air Heater. Combined Fan and ...	February	26	Automatic Condensate Drainage ...	May	66
Air Heater. Improved Ljungstrom ...	October	137	Auxiliary Engines for Liner. Two 1,660 b.h.p. ...	January	13
Air Register. Nozzle-type Boiler ...	April	45	Auxiliary Oil Engines. Fuels for Marine ...	April	52
Air-activated Gravity Conveyors. Vessel Unloading with ...	February	17	Axial-flow Compressor. Wet Compression in ...	October	131
Airborne Lifeboat. Radio Control for ...	July	96	Backing for Tube Joints. Ceramic ...	September	116
Allen Gas Turbine ...	January	2	Bacterial Action. Ship Corrosion Due ...	May	72
Alloy for Elevated Temperature Service. Aluminium ...	November	142	Ball Bearings. Corrosion of ...	October	133
Alloy Lifeboat. Light ...	September	128	Ballast and Bilge Water. De-oiling of ...	August	105
Alloy. Scantlings of Long Deckhouses of Aluminium ...	July	97	Baltic Passenger Steamship ...	November	141
Alloys. Creep Tests on Nimonic ...	December	163	Barge. Diesel-electric ...	June	76
Alloys in Marine Atmosphere. Behaviour of Light ...	February	17	Barge. Petroleum ...	January	9
Alloys. Stud Welding on Aluminium ...	January	2	Basic Engineering Standards...	September	118
Aluminium Alloy for Elevated Temperature Service ...	November	142	Bauer-Wach Turbine. Steamship with ...	May	60
Aluminium Alloy. Scantlings of Long Deckhouses of ...	July	97	Bauxite Carrier. Self-unloading ...	December	167
Aluminium Alloys. Stud Welding on ...	January	2	Beams. Inelastic Strains in Steel ...	July	100
Aluminium as Shipbuilding Material ...	May	70	Beams. Residual Stress and Yield Strength of Steel ...	July	90
Aluminium. Bonding Rubber to ...	November	147	Bearing Performance. Sleeve ...	September	128
Aluminium Coatings. Sprayed ...	September	118	Bearings. Corrosion of Ball ...	October	133
Aluminium Heat Exchangers. Brazed ...	March	38	Bearings. Foreign Particles in Sleeve ...	September	128
Aluminium on Creep Properties. Influence of ...	December	163	Behaviour as Influenced by Surface Condition. Chemical ...	December	166
Aluminium Ore Carriers ...	July	96	Behaviour of Light Alloys in Marine Atmosphere ...	February	17
Aluminium Paint in Marine Use ...	March	42	Bending Loads. Effective Breadth of Stiffened Plating under ...	March	32
Aluminium Rivets. Cold Driven Large ...	July	99	Bent Plate Sheerstrake in Tankers ...	December	159
American Bureau of Shipping. Annual Meeting of ...	May	64	Bilge Pump Explodes ...	May	60
American Diesels. Burning Bunker Oils in ...	February	22	Bilge Water. De-oiling of Ballast and ...	August	105
American Research Projects ...	September	114	Blade Clearance. Adjusting Gas Turbine ...	October	133
Amyl Nitrate as Ignition Accelerator ...	June	80	Blade. Removal of Propeller...	June	76
			Blade Vibration. Gas Turbine ...	November	147

	Issue	Page		Issue	Page
Blading. Steam Flow through Turbine			Cargoes. Moisture Damage to	April	46
Nozzles and	August	102	Carrier. Self-unloading Bauxite	December	167
Blower. Compression Work in Roots'	June	77	Cast Iron. Stud Welding	March	35
Blowers. Forced Draught	January	7	Cathodic Currents. Reducing Corrosion by	April	53
Boiler Air Register. Nozzle-type	April	45	Caulking Compound. Deck...	August	101
Boiler. Closed Feed System for	April	54	Cavitation. Photography at Sea of Propeller	January	5
Boiler Controls. Marine	August	112	Centrifugal Cargo Pump for Tankers	July	88
Boiler Deposits. External	October	137	Centrifugal Pumps in Steam Power Stations	May	66
Boiler Design. Marine	January	9	Ceramic Backing for Tube Joints	September	116
Boiler Design. New	August	111	Ceramic Protective Coating. Refractory	December	166
Boiler Feed System	February	27	Chemical Behaviour as Influenced by Surface		
Boiler Fuel. Engine Operation on	July	87	Condition	December	166
Boiler Makeup. Demineralizing	April	56	Chemical Reactions in Diesel Engine	August	108
Boiler Materials. Testing of Steam	July	86	Chilean Ore Carrier	August	106
Boiler. New Exhaust for Gas	July	86	Chilling of Diesel Engines	June	79
Boiler-oil as Standard Fuel	March	33	Chromium-molybdenum Steel Pipe. Arc		
Boiler Oil. Economy with	September	115	Welding of Low	November	145
Boiler-oil Fuel System for the <i>Aureol</i>	March	31	Chromizing	March	42
Boiler Scale Fuel Losses	August	112	Circuit. Economizer	January	5
Boiler Slagging. Oil Additive to Relieve	October	139	<i>Ciudad de Medellin</i> . Cargo Motorship	February	20
Boiler Test Plant. U.S. Navy Expands	June	81	Clad Steels. Stainless...	May	70
Boiler. True Water Level in...	September	113	Clamp for Tanker Lines. New	September	115
Boiler. Two-furnace	May	65	Clamping System. New Wire-rope...	August	103
Boilers. Automatic Combustion Control for			Cleaning Marine Turbine Lubricating System	August	103
Marine	January	16	Cleaning. New Method of Tank	June	76
Boilers. Desuperheater for Stage-type	May	69	Closed Feed System for Boiler	April	54
Bolt. Self-sealing One-way	March	33	Coaster. New Motor...	November	153
Bonding Rubber to Aluminium	November	147	Coasters. Form Variations of Fast	May	67
Bottoms. Protection of Inactivated Ship	June	73	Coating. Refractory Ceramic Protective	December	166
Brazed Aluminium Heat Exchangers	March	38	Coatings. Corrosion Resistant Tank	September	118
Brazing. High Strength Vacuum	December	162	Coatings. Fused Metallized...	April	49
Breadth of Stiffened Plating under Bending			Coatings. Gasolene Resistant Tank	June	73
Loads. Effective...	March	32	Coatings on Metals. Protective	February	20
Bridges. Design of Wheelhouses and	April	50	Coatings. Sprayed Aluminium	September	118
Bronze-surfacing	July	100	Cold Driven Large Aluminium Rivets	July	99
Buckling Problems. Study of	October	130	Cold Rolled Fillets	October	129
Bulge Explosion Test. Testing Welds by	February	19	Collection System. Condensate	December	157
Bulkhead Intersections for Welded Tankers	May	63	Combating Corrosion in Tankers	July	100
Bunker Oils in American Diesels. Burning	February	22	Combined Fan and Air Heater	February	26
Buoy. Radio Dan	November	147	Combined Steam and Gas Turbine	December	165
Bureau of Shipping. Annual Meeting of			Combustion Control for Marine Boilers.		
American	May	64	Automatic...	January	16
Bureau Veritas Rules	January	12	Combustion in Gas Turbines	April	52
Burning Bunker Oils in American Diesels	February	22	Compound to Improve Diesel Fuel	January	13
Cable Ship. New French	January	3	Compressed Air Arc Torch	May	71
C-3 Ships. New Propeller Designs for			Compression Engine. Constant	July	94
Victory and	October	135	Compression in Axial-flow Compressor. Wet	October	131
Cable Steamship. Twin-screw	October	136	Compression-operated Fuel Pumps	October	135
Cadmium Fume Hazard	January	14	Compression Work in Roots' Blower	June	77
Calculation of Rectangular Bar Helical			Compressor. Free Piston Air	November	153
Springs	July	90	Compressor. Wet Compression in Axial-		
Calculator. Götaverken Tanker Load	January	11	flow	October	131
Carbon Steels. Sigma Welding of	March	35	Condensate Collection System	December	157
Cargo Boat. Refrigerated French	May	68	Condensate Drainage. Automatic	May	66
Cargo Handling in Wet Weather	February	27	Condensation. Preventing	September	126
Cargo Handling Methods. Modern	June	83	Condenser. Evershed Straub Degassing	January	14
Cargo Hoist. Adjustable Voltage	January	8	Condenser Scoop. Problem of the	December	160
Cargo Liner. 14,000-ton Refrigerated	October	138	Condenser Systems. Corrosion in	October	140
Cargo Liner. German-built Dutch...	October	138	Constant Compression Engine	July	94
Cargo Liner. Modern Japanese	November	154	Control Device for Voith Schneider Pro-		
Cargo Liner. New German	September	115	peller	November	141
Cargo Liner. Twin-screw	August	112	Control. Superheat	March	44
Cargo Liners. High-powered Single-screw	May	68	Controllable Pitch Propeller	August	102
Cargo Motorship <i>Ciudad de Medellin</i>	February	20	Controlled Density Steel	March	41
Cargo Motorship for I.O.M. Owners	May	71	Conveyors. Vessel Unloading with Air-		
Cargo Motor Ship. Swiss	December	161	activated Gravity...	February	17
Cargo Oil Tanks. Venting	January	6	Cooled Rotor for Gas Turbine	May	57
Cargo Pump for Tankers. Centrifugal	July	88	Corrosion by Cathodic Currents. Reducing	April	53
Cargo Vessel for Arctic Service	July	95	Corrosion Due to Bacterial Action. Ship	May	72
Cargo Vessel. Gas Turbine for	March	34	Corrosion in Condenser Systems	October	140
Cargoes. Dangerous	September	117	Corrosion in Tankers. Combating	July	100
			Corrosion of Ball Bearings	October	133

	Issue	Page		Issue	Page
Corrosion Protection by Metallizing...	May	72	Diesel Engines. Chilling of ...	June	79
Corrosion Resistant Tank Coatings ...	September	118	Diesel Engines for Large Tankers ...	February	24
Corrosion. Spring Failures by ...	September	118	Diesel Engines. Marine ...	August	102
Corrosion Testing ...	March	42	Diesel Engines. Novel Pressure Charger for	May	60
Corrosion Testing. Coupon Technique in	June	73	Diesel Engines in Service. Instrumentation		
Corrosive Resistance of Titanium ...	September	118	for ...	July	86
Coupling. Torsional Vibration of Flexible	December	161	Diesel Engines. Pressure charging of Four-		
Couplings. Electro-magnetic ...	September	121	stroke ...	November	151
Couplings. Twofold Use of Magnetic ...	February	22	Diesel Engines. Sulphurous Fuels for ...	September	116
Coupon Technique in Corrosion Testing ...	June	73	Diesel Fuel. Compound to Improve ...	January	13
Crack Detection. New Fluorescent Ink for	December	165	Diesel Knock. Injection Characteristics and	September	123
Crack Resistance in Ships. Improving ...	December	158	Diesel Machinery. Pressure-charged Vee-type	May	65
Crankcase Explosions. Suppressing...	August	108	Diesel Parts. Reclaiming Used ...	April	46
Crankcases. Explosions in Enclosed ...	June	79	Diesel Passenger Ships. Geared ...	March	40
Crankshaft. Hydrogen Foam from...	November	150	Diesel Plant for Residual Fuel. Marine ...	December	160
Crankshaft Journals <i>in situ</i> . Machining ...	November	148	Diesel Trawler... ..	September	127
Crankshafts. Failure of Shrink Fits in ...	October	129	Diesels. Burning Bunker Oils in American	February	22
Creep as a Surface-dependent Phenomenon	January	15	Dilastrain Method	April	47
Creep of Superheater and Pipe Steels ...	December	162	Dimensional Effects in Fracture ...	May	60
Creep Properties. Influence of Aluminium			Direction of Rolling on Properties of Steel		
on	December	163	Plates. Effect of... ..	December	164
Creep Tests on Nimonic Alloys	December	163	Disks in Pure Sliding. Rotating	January	7
Cross-Channel Steamship. New	May	57	Double Acting Diesel Engine. Large ...	August	109
Currents. Reducing Corrosion by Cathodic	April	53	Double-acting Engines. Ports for ...	June	77
Cylinders. Flexural Vibrations of Thin ...	October	130	Double-compound Engines. Improved ...	May	61
			Double Reduction Gear. Locked Train ...	May	64
Damage due to Vibration	February	20	Doxford Engine. First Australian-built ...	February	25
Dangerous Cargoes	September	117	Doxford Engine. Turbo-charged	September	123
Danish-built Tanker for Russia	September	127	Drainage. Automatic Condensate	May	66
Danish Motor Ship. New	June	75	Dredge for Indonesia. Diesel	October	136
Davit for Merchant Ships. New	April	51	Dredger... ..	March	39
Davits. Shepers	June	77	Dredger. Diesel Electric	May	68
Deck Caulking Compound	August	101	Drifter Trawlers	April	48
Deckhouses of Aluminium Alloy. Scantlings			Drill. Use of Welding Torch as	June	77
of Long	July	97	Drydocking. Keel Block Loads during ...	October	138
Deep Sea Salvage Tug	April	47	Drying by Granular Adsorbents. Air ...	May	58
Defects. Non-destructive Investigation of			Dutch Cargo Liner. German-built	October	138
Surface	December	164	Dynamic Selector Winch	October	135
Definitions for Internal Combustion Engines	March	44	Dynamometers and Engine Test Plant ...	September	116
Degassing Condenser. Evershed Straub ...	January	14			
Deminerlizing Boiler Makeup	April	56	<i>Ebro</i> . Single-screw Motorship	December	159
Denmark and Holland to Build Ships for			Economizer Circuit	January	5
Russia	April	50	Economy with Boiler Oil	September	115
De-oiling of Ballast and Bilge Water ...	August	105	Effect of Direction of Rolling on Properties		
Deposits. External Boiler	October	137	of Steel Plates	December	164
Design and Manufacture of Ships' Propellers	January	15	Effect of Lubrication and Forms of Wear	December	162
Design for Tugs. Propeller	September	120	Effect of Freezing on Manila Rope	January	1
Design of Trawler's Fishroom	September	120	Effective Breadth of Stiffened Plating under		
Design of Tube Plates for Heat Exchangers	July	98	Bending Loads	March	32
Design of Wheelhouses and Bridges... ..	April	50	Egypt. Motorships for	April	51
Designs for Victory and C-3 Ships. New			Electric Circuits on Passenger Vessels.		
Propeller	October	135	Single-pole	January	15
Desuperheater for Stage-type Boilers ...	May	69	Electric-hydraulic Drive. Winch with ...	February	24
Detection of Flaws in Metal. X-Ray	December	163	Electric Resistance Strain Gauge. New ...	May	72
Detergency Lubricants. High	July	89	Electrical Pretreatment of Water	September	125
Detergent Lubricants. Use of	March	33	Electro-magnetic Couplings	September	121
Determination of Moments in Rigid Plates	July	92	Electronic Ship's Whistle	September	114
Diesel Dredge for Indonesia... ..	October	136	Enclosed Crankcases. Explosions in ...	June	79
Diesel-electric Barge	June	76	Engine Cooling with Vapour Phase	November	150
Diesel Electric Dredger	May	68	Engine Operation on Boiler Fuel	July	87
Diesel Engine—(I). Highly Supercharged			Epicyclic Gears	April	52
M.A.N.	May	58	Equipment for Gas Turbine Rotor Inspection.		
Diesel Engine. Admiralty Range II	June	82	X-ray	December	168
Diesel Engine. Chemical Reactions in ...	August	108	Estimation of Ship's Engine Power from		
Diesel Engine. Improved Medium Speed ...	March	43	Model Results	February	23
Diesel Engine Features. New Sulzer	November	146	Evaporating Fluids in Pipes. Flow of ...	April	55
Diesel Engine. Large Double Acting	August	109	Evaporator Plants	May	59
Diesel Engine. New Marine... ..	August	107	Evershed-Straub Degassing Condenser ...	January	14
Diesel Engine Operation	August	111	Exchangers. Design of Tube Plates for Heat	July	98
Diesel Engine. Repair of a	December	168	Exhaust for Gas Boiler. New	July	86
Diesel Engine Starting	June	80	Explosion Test. Testing Welds by Bulge	February	19
Diesel Engine. Two-stroke Marine	September	125			

	Issue	Page		Issue	Page
Explosions in Enclosed Crankcases ...	June	79	Funnel. Improved Ship's ...	January	11
Explosions. Suppressing Crankcase...	August	108	Funnels for New Swedish Liner ...	November	148
External Boiler Deposits ...	October	137	Furnace Efficiency. Flame Radiation and ...	August	112
Failure of a High Pressure Turbine Shaft	June	75	Fused Metallized Coatings ...	April	49
Failure of Shrink Fits in Crankshafts ...	October	129	Gas and Hydraulic Turbine Drive ...	January	7
Failures by Corrosion. Spring ...	September	118	Gas Boiler. New Exhaust for ...	July	86
Failures. Reducing Shaft ...	May	62	Gas Conduction in Fibrous Installation.		
Fan and Air Heater. Combined ...	February	26	Heat Transfer by...	October	140
Fast Coasters. Form Variations of...	May	67	Gas Turbine. Allen ...	January	2
Fatigue Strength of Stiffened Panels ...	October	130	Gas Turbine Blade Clearance. Adjusting ...	October	133
Fatigue Testing Installation. Large ...	February	17	Gas Turbine Blade Vibration...	November	147
Features of 250-kW. Marine Gas Turbine ...	March	36	Gas Turbine. Combined Steam and ...	December	165
Feed System. Boiler ...	February	27	Gas Turbine Control...	October	132
Feed System for Boiler. Closed ...	April	54	Gas Turbine. Cooled Rotor for ...	May	57
Ferry. Ice-breaking ...	May	67	Gas Turbine. Features of 250-kW. Marine	March	36
Ferry. New Swedish...	January	2	Gas Turbine for Cargo Vessel ...	March	34
Fibre. New Refractory ...	November	151	Gas Turbine from the Viewpoint of an Aero-		
Fibrous Installation. Heat Transfer by Gas			nautical Engineer. Marine ...	March	36
Conduction in ...	October	140	Gas Turbine. Inward-flow Radial ...	December	164
Fillets. Cold Rolled ...	October	129	Gas Turbine. Light-weight...	October	131
Filters. Oil ...	July	89	Gas Turbine Operating Experience ...	December	165
Fire Prevention in Ships under Repair ...	August	104	Gas Turbine Plant in 1951. Marine ...	March	38
Fire Prevention under the 1948 Convention	July	100	Gas Turbine Plant. Solid Fuel Fired ...	October	140
First Australian-built Doxford Engine ...	February	25	Gas Turbine Progress...	October	132
First Vessel with "Active Rudder" ...	September	119	Gas Turbine Rotor Inspection. X-ray		
Fish Detection. New Device for ...	April	54	Equipment for ...	December	168
Fishery Research Trawler ...	June	75	Gas Turbine. Simple 400-horsepower ...	March	37
Fishroom. Design of Trawler's ...	September	120	Gas Turbine. Small ...	February	21
Flame Radiation and Furnace Efficiency ...	August	112	Gas Turbine. Small ...	October	132
Flame Radiation Research ...	February	27	Gas Turbine Test. Results in 1,000 kW. ...	October	132
Flaw Detector. New Ultrasonic ...	July	93	Gas Turbines. Combustion in ...	April	52
Flaws in Metal. X-ray Detection of ...	December	163	Gasolene Resistant Tank Coatings ...	June	73
Flexure of Steel Beams. Plastic ...	February	18	Gauge. New Electric Resistance Strain ...	May	72
Flexible Coupling. Torsional Vibration of	December	161	Gear. Locked Train Double Reduction ...	May	64
Flexural Vibrations of Thin Cylinders ...	October	130	Gear Lubricants. Prediction of Service Per-		
Flow of Evaporating Fluids in Pipes ...	April	55	formance of ...	December	160
Flow Patterns. Photographing ...	October	134	Gear-oil Additives ...	January	6
Fluids for Hydraulic Power Transmission ...	January	7	Gear Scuffing ...	October	139
Fluorescent Ink for Crack Detection. New	December	165	Gear-tooth Stress and Rating Formulæ ...	April	49
Foam from Crankshaft. Hydrogen...	November	150	Gear Tooth Wear ...	October	139
Forced Draught Blowers ...	January	7	Geared Diesel Passenger Ships ...	March	40
Foreign Particles in Sleeve Bearings...	September	128	Geared Motorship <i>Waimate</i> ...	January	12
Form Variations of Fast Coasters ...	May	67	Geared Turbines. Latest ...	August	109
Four-stroke Diesel Engines. Pressure charg-			Geared Turbines of 1,500 s.h.p. ...	August	107
ing of ...	November	151	Gearing. Large Reverse Reduction ...	May	64
Fracture. Dimensional Effects in ...	May	60	Gears. Epicyclic ...	April	52
Fracture of Marine Shafting...	March	39	Gears. Materials for Propulsion ...	August	102
Fracture Problem. Ship ...	July	96	Gears. Removal of Engine ...	July	94
Frames for Multi-crankshaft Engines ...	July	87	Generators. Shaft Drive for...	February	19
Free Piston Air Compressor ...	November	153	German-built Dutch Cargo Liner ...	October	138
Free-piston Engines. Minesweepers with			German Cargo Liner. New ...	September	115
Pescara ...	April	50	German Steam Turbine Propulsion Plant ...	February	18
Freezing on Manila Rope. Effect of ...	January	1	Gerritsen Gear...	February	21
Freighter. Reheated Engine in Norwegian	June	81	Glass Insulation ...	April	47
French Cable Ship. New ...	January	3	Götaverken Tanker Load Calculator...	January	11
French Cargo Boat. Refrigerated ...	May	68	Granular Adsorbents. Air Drying by ...	May	58
French Passenger Liner ...	May	69	Graphite Impregnated Rubber Packing for		
French Passenger Liner. New ...	February	19	Pumps ...	February	22
French Passenger Steamship...	July	95	Gravity Conveyors. Vessel Unloading with		
Fuel. Boiler-oil as Standard...	March	33	Air-activated ...	February	17
Fuel. Compound to Improve Diesel ...	January	13	Gyroscope. Motion Due to Slow Precession		
Fuel Consumption. Motor Tanker's Low ...	May	65	of a ...	June	74
Fuel. Engine Operation on Boiler ...	July	87	Hard Facing for Impact ...	April	56
Fuel Losses. Boiler Scale ...	August	112	Hard Metals. Spark Machining ...	September	117
Fuel. Marine Diesel Plant for Residual ...	December	160	Heat Exchangers. Brazed Aluminium ...	March	38
Fuel Pumps. Compression-operated ...	October	135	Heat Exchangers. Design of Tube Plates for	July	98
Fuel System for the <i>Aureol</i> . Boiler-oil ...	March	31	Heat Transfer by Gas Conduction in Fibrous		
Fuels for Marine Auxiliary Oil Engines ...	April	52	Installation ...	October	140
Fuels for Medium-sized Marine Engines.			Heat Transfer Inside Tubes ...	February	22
Heavy ...	April	46	Heater. Combined Fan and Air ...	February	26
Fume Hazard. Cadmium ...	January	14			

	Issue	Page		Issue	Page
Heavy Fuels for Medium-sized Marine Engines	April	46	Jointings. Pipe Flange	January	4
Helical Springs. Calculation of Rectangular Bar	July	90	Joints between Dissimilar Materials. Welded Pipe	January	10
High Detergency Lubricants... ..	July	89	Joints. Ceramic Backing for Tube	September	116
High-powered Single-screw Cargo Liners ...	May	68	Journals <i>in situ</i> . Machining Crankshaft ...	November	148
High-pressure Service. Joining of Dissimilar Metals for High-temperature	January	13	Keel Block Loads during Drydocking ...	October	138
High Pressure Turbine Shaft. Failure of a High Speed Vessel. Novel	June	75	Knock. Injection Characteristics and Diesel Kort Nozzle. Improved	September	123
High Strength Vacuum Brazing	September	113	Kort Nozzle. New	April	53
High-temperature High-pressure Service. Joining of Dissimilar Metals for	December	162	Lake Motorship. Swiss	August	101
High-wear Resistance Materials	January	13	Landing Craft. Plastic	March	36
Highly Supercharged M.A.N. Diesel Engine—(I)	November	143	Large Double Acting Diesel Engine	November	156
H.M. Ships in Tropical Waters. Thermal Conditions in	August	109	Large Fatigue Testing Installation	August	109
Hoist. Adjustable Voltage Cargo	February	17	Large Reverse Reduction Gearing	February	17
Holland to Build Ships for Russia. Denmark and	May	58	Large Tankers... ..	May	64
Hulls. Strengthening of T2... ..	June	83	Largest Motor Tanker	February	20
Human Stress from a Marine and Naval Viewpoint. Studies of	July	98	Largest Quarterdecker Motorship	July	98
Hydraulic Power Transmission. Fluids for Hydraulic Turbine Drive. Gas and	October	8	Largest Scandinavian Ship	October	136
Hydraulically Controlled Trawl Winch ...	April	50	Largest Scandinavian Vessel... ..	May	69
Hydrofoils. Possibilities of	September	125	Largest Tanker	September	115
Hydrogen Foam from Crankshaft	June	74	Largest Tanker	July	98
Hydromechanics Research	August	103	Latest Geared Turbines	August	109
Icebreaker. Small	January	7	Lifeboat. Light Alloy	September	128
Ice-breaker. Swedish... ..	January	7	Lifeboat. Radio Control for Airborne ...	July	96
Icebreakers. Machinery for	September	127	Lifts in Ships	March	39
Icebreakers. Model Tests with	September	122	Light Alloy Lifeboat	September	128
Ice-breaking Ferry	January	1	Light Alloys in Marine Atmosphere. Behaviour of	February	17
Ignition Accelerator. Amyl Nitrate as Impact. Hard Facing for	November	150	Light-weight Gas Turbine	October	131
Improved Double-compound Engines ...	April	55	Ljungstrom Air Heater. Improved... ..	October	137
Improved Kort Nozzle	April	53	Load Calculator. Götaverken Tanker ...	January	11
Improved Ljungstrom Air Heater	October	137	Loads. Effective Breadth of Stiffened Plating under Bending	March	32
Improved Medium Speed Diesel Engine ...	March	43	Loading. Stress Finder for Ship's	September	121
Improved Safety Valve	March	41	Locked Train Double Reduction Gear ...	May	64
Improved Scavenging System	September	124	Low Fuel Consumption. Motor Tanker's... ..	May	65
Improved Ship's Funnel	January	11	Lubricants. High Detergency	July	89
Improving Crack Resistance in Ships ...	December	158	Lubricants. Prediction of Service Performance of Gear	December	160
Inactivated Ship Bottoms. Protection of ...	June	73	Lubricants. Use of Detergent	March	33
Indicator. Shaft Rotation	August	101	Lubricating Oil. Reconditioning	January	16
Indonesia. Diesel Dredge for	October	136	Lubrication System. Cleaning Marine Turbine	August	103
Inelastic Strains in Steel Beams	July	100	Lubrication and Forms of Wear. Effect of ...	December	162
Influence of Aluminium on Creep Properties	December	163	Machinery Aft. Passenger Steamship with ...	November	143
Influence of Support upon Critical Speed of Rotor	February	24	Machinery for Icebreakers	November	150
Injection Characteristics and Diesel Knock... ..	September	123	Machining Crankshaft Journals <i>in situ</i> ...	November	148
Ink for Crack Detection. New Fluorescent Inspection. X-ray Equipment for Gas Turbine Rotor	December	168	Magnesium Anodes	July	92
Instrumentation for Diesel Engines in Service	July	86	Magnetic Couplings. Twofold Use of M.A.N. Diesel Engine—(I). Highly Supercharged	February	22
Insulation. Glass	April	47	Manila Rope. Effect of Freezing on	May	58
Insulation. Sprayed Asbestos	March	42	Manufacture of Ship Propellers	January	1
Internal Combustion Engines. Definitions for	March	44	Marine Boiler Controls	February	23
Inward-flow Radial Gas Turbine	December	164	Marine Boiler Design... ..	August	112
I.O.M. Owners. Cargo Motorship for ...	May	71	Marine Diesel Engines	January	9
Iron. Stud Welding Cast	March	35	Marine Diesel Plant for Residual Fuel ...	August	102
Italian Ships for Soviet Union	November	155	Marine Diesel Plant for Residual Fuel ...	December	160
Japan. Tanker Built in	April	53	Marine Fans	March	37
Japanese Cargo Liner. Modern	November	154	Marine Gas Turbine from the Viewpoint of an Aeronautical Engineer	March	36
Japanese Shipbuilding	April	50	Marine Gas Turbine Plant in 1951	March	38
Joining of Dissimilar Metals for High-Temperature High-pressure Service	January	13	Marine Power Plant	September	120
			Masts. Tests on Stayed and Unstayd ...	December	160
			Materials for Advanced Steam Conditions. Steam Pipe	June	83
			Materials for Propulsion Gears	August	102
			Measurement of Ventilation by Radioactive Tracers	July	92
			Medium-sized Marine Engines. Heavy Fuels for	April	46

	Issue	Page		Issue	Page
Medium Speed Diesel Engine. Improved...	March	43	New Steering Control System	February	19
Merchant Ships. New Davit for	April	51	New Sulzer Diesel Engine Features	November	146
Metal Spraying. Application of Ultrasonics to	July	92	New Super Tankers	July	91
Metal Spraying Process. New Uses of	March	41	New Swedish Ferry	January	2
Metals. Sea Water Spray Testing of	January	16	New Swedish Liner. Funnels for	November	148
Metals. Spark Machining Hard	September	117	New Ultrasonic Flaw Detector	July	93
Metallized Coatings. Fused... ..	April	49	New Uses of Metal Spraying Process	March	41
Metallizing	July	91	New Wire-rope Clamping System	August	103
Metallizing. Corrosion Protection by	May	72	New Zinc Coating Process	November	147
Metastable Flow of Saturated Water	January	15	Nimonic Alloys. Creep Tests on	December	163
Meter. Remote Reading Mechanical	January	15	Nine Rudders. Towboat with	May	67
Microstructure of Ship Plate Steel	April	56	Nodal Pattern Analysis	April	55
Mild-steel Pipe. Residual Stresses in Welded	January	2	Non-destructive Investigation of Surface Defects	December	164
Milling Machine. Propeller... ..	February	18	Non-magnetic Ship Model Laboratory	March	36
Minesweepers with Pescara Free-piston Engines	April	50	Norwegian Freighter. Reheated Engine in	June	81
Minimum Weight of Structural Parts	March	31	Norwegian Tanker	December	168
Model Laboratory. Non-magnetic Ship	March	36	Notch Bar Testing to Welded Construction. Relation of	March	29
Model Results. Estimation of Ship's Engine Power from	February	23	Novel Equipment. Small Ship with	November	152
Model Tests with Icebreakers	September	127	Novel High Speed Vessel	September	113
Modern Cargo Handling Methods	June	83	Novel Pressure Charger for Diesel Engines	May	60
Modern Japanese Cargo Liner	November	154	Nozzle. Improved Kort	April	53
Moisture Damage to Cargoes	April	46	Nozzle. New Kort	August	101
Moments in Rigid Plates. Determination of	July	92	Nozzle Propeller	April	55
Motion Due to Slow Precession of a Gyroscope	June	74	Nozzle-type Boiler Air Register	April	45
Motor Coaster. New... ..	November	153	Observations on Experience with Welded Ships	November	143
Motorship <i>Ciudad de Medellin</i> . Cargo	February	20	Oil Atomizers. Steam	July	94
Motorship <i>Ebro</i> . Single-screw	December	159	Oil. Additive to Relieve Boiler Slagging	October	139
Motorship for I.O.M. Owners. Cargo	May	71	Oil. Economy with Boiler	September	115
Motorship. Largest Quarterdecker	October	136	Oil Engines. Fuels for Marine Auxiliary	April	52
Motor Ship. New Danish	June	75	Oil Filters	July	89
Motorship. Single-screw	December	158	Oil. Reconditioning Lubricating	January	16
Motorship. Swiss	September	128	Oil Tanks. Venting Cargo	January	6
Motor Ship. Swiss Cargo	December	161	Oils in American Diesels. Burning Bunker	February	22
Motorship. Swiss Lake	March	36	On the Waves of Ships	November	156
Motorship <i>Waimate</i> . Geared	January	12	One-way Bolt. Self-sealing	March	33
Motorship with Engines Aft... ..	March	32	Opposed Piston Engine	August	110
Motorships for Egypt	April	51	Opposed-piston Engine	January	4
Motor Tanker. Largest	July	98	Optimum Single Propellers	October	134
Motor Tanker's Low Fuel Consumption	May	65	Ore Carrier. Chilean	August	106
Motor Vessel with Special Features... ..	November	151	Ore Carriers. Aluminum	July	96
Multi-crankshaft Engines. Frames for	July	87	Oxyacetylene Welding. Safe Practice in	January	7
New Boiler Design	August	111	Paint in Marine Use. Aluminium	March	42
New Clamp for Tanker Lines	September	115	Paints. Anti-corrosion	April	46
New Cross-Channel Steamship	May	57	Panels. Fatigue Strength of Stiffened	October	130
New Danish Motor Ship	June	75	Passenger Liner. French	May	69
New Davit for Merchant Ships	April	51	Passenger Liner. New	July	95
New Device for Fish Detection	April	54	Passenger Liner. New French	February	19
New Electric Resistance Strain Gauge	May	72	Passenger Ships. Geared Diesel	March	40
New Exhaust for Gas Boiler	July	86	Passenger Steamship. Baltic... ..	November	141
New Fluorescent Ink for Crack Detection	December	165	Passenger Steamship. French	July	95
New French Cable Ship	January	3	Passenger Steamship with Machinery Aft	November	143
New French Passenger Liner	February	19	Pattern Analysis. Nodal	April	55
New German Cargo Liner	September	115	Patterns. Photographing Flow	October	134
New Kort Nozzle	August	101	Performance of s.s. <i>Schuyler Otis Bland</i>	June	83
New Marine Diesel Engine	August	107	Pescara Free-piston Engines. Minesweepers with	April	50
New Method of Rust Protection	March	38	Petroleum Barge	January	9
New Method of Tank Cleaning	June	76	Phase. Engine Cooling with Vapour	November	150
New Motor Coaster	November	153	Photographing Flow Patterns	October	134
New Passenger Liner	July	95	Photography at Sea of Propeller Cavitation	January	5
New Propeller Designs for Victory and C-3 Ships	October	135	Pipe. Arc Welding of Low Chromium-molybdenum Steel	November	145
New Radial Engine	September	122	Pipe Flange Jointings... ..	January	4
New Refractory Fibre... ..	November	151	Pipe Joints between Dissimilar Materials. Welded	January	10
New Research Station... ..	December	161	Pipe Materials for Advanced Steam Conditions. Steam	June	83
New Seatrain Vessels	February	28			
New Sludge Vessel	April	55			

	Issue	Page		Issue	Page
Pipe. Residual Stresses in Welded Mild-steel	January	2	Pump and Turbo Blower. Werkspoor Engine		
Pipe Steels. Creep of Superheater and ...	December	162	with Scavenging	February	21
Pipes. Flow of Evaporating Fluids in ...	April	55	Pump Explodes. Bilge	May	60
Pitch Propellers. Tests on Variable ...	October	136	Pump for Tankers. Centrifugal Cargo ...	July	88
Pitting. Preventing Propeller	October	133	Pumps. Compression-operated Fuel ...	October	135
Plane Surfaces in Turbulent Flow. Smooth	July	88	Pumps. Graphite Impregnated Rubber Pack-		
Plants. Evaporator	May	59	ing for	February	22
Plastic Flexure of Steel Beams	February	18	Pumps in Steam Power Stations. Centrifugal	May	66
Plastic Landing Craft... ..	November	156	Pusher Tug. Twin Screw Motor	July	89
Plastic Theory Applied to Strain Hardening	February	18	Quarterdecker Motorship. Largest... ..	October	136
Plasticity Research	February	18	Radial Engine. New	September	122
Plate Sheerstrake in Tankers. Bent	December	159	Radial Gas Turbine. Inward-flow	December	164
Plate Steel. Microstructure of Ship ...	April	56	Radiation Errors. Reducing Probe	October	134
Plates. Determination of Moments in Rigid	July	92	Radiation Research. Flame	February	27
Plates. Effect of Direction of Rolling on			Radio Control for Airborne Lifeboat ...	July	96
Properties of Steel	December	164	Radio Dan Buoy	November	147
Plating under Bending Loads. Effective			Radioactive Tracers. Measurement of Ven-		
Breadth of Stiffened	March	32	tilation by... ..	July	92
Polyamide-clad Wire Rope	March	35	Range I Engine. Admiralty Standard ...	February	26
Pontoons. Tilting	October	138	Range II Diesel Engine. Admiralty ...	June	82
Ports for Double-acting Engines	June	77	Rating Formulæ. Gear-tooth Stress and ...	April	49
Possibilities of Hydrofoils	January	1	Reclaiming Used Diesel Parts	April	46
Power Plant. Marine... ..	September	120	Reconditioning Lubricating Oil	January	16
Power Stations. Centrifugal Pumps in Steam	May	66	Recorder. Torsional Vibration	September	114
Precession of a Gyroscope. Motion Due to			Rectangular Bar Helical Springs. Calcula-		
Slow	June	74	tion of	July	90
Prediction of Service Performance of Gear			Reducing Corrosion by Cathodic Currents ...	April	53
Lubricants	December	160	Reducing Probe Radiation Errors	October	134
Prefabricated Propeller	June	77	Reducing Shaft Failures	May	62
Pressure Charging of Four-stroke Diesel			Refractory Ceramic Protective Coating ...	December	166
Engines'	November	151	Refractory Fibre. New	November	151
Pressure Control. Ventilation	July	99	Refrigerated Cargo Liner. 14,000-ton ...	October	138
Pretreatment of Water. Electrical	September	125	Refrigerated French Cargo Boat	May	68
Preventing Condensation	September	126	Reheated Engine in Norwegian Freighter ...	June	81
Preventing Marine Corrosion by Metallizing	November	147	Reinforced Steel Tubing	October	130
Prevention in Ships under Repair. Fire ...	August	104	Relation of Notch Bar Testing to Welded		
Prevention under the 1948 Convention. Fire	July	100	Construction	March	29
Pressure-charged Vee-type Diesel Machinery	May	65	Remote Reading Mechanical Meter	January	15
Pressure Charger for Diesel Engines. Novel	May	60	Removal of Engine Gears	July	94
Preventing Propeller Pitting	October	133	Removal of Propeller Blade	June	76
Probe Radiation Errors. Reducing	October	134	Repair of a Diesel Engine	December	168
Problem of the Condenser Scoop	December	160	Research. Flame Radiation	February	27
Propeller Blade. Removal of	June	76	Research. Plasticity	February	18
Propeller Cavitation. Photography at Sea of	January	5	Research Projects. American	September	114
Propeller. Control Device for Voith			Research Ship. Wave Recorder in	July	96
Schneider	November	141	Research Station. New	December	161
Propeller. Controllable Pitch	August	102	Research Trawler. Fishery	June	75
Propeller Design for Tugs	September	120	Residual Fuel. Marine Diesel Plant for ...	December	160
Propeller Designs for Victory and C-3 Ships.			Residual Stress and Yield Strength of Steel		
New	October	135	Beams	July	90
Propeller Milling Machine	February	18	Residual Stresses in Welded Mild-steel Pipe	January	2
Propeller. Nozzle	April	55	Resistance and Propulsive Power	March	32
Propeller Pitting. Preventing	October	133	Resistance Materials. High-wear	November	143
Propeller. Prefabricated	June	77	Resistance Strain Gauge. New Electric ...	May	72
Propeller. Six-bladed	March	43	Results in 1,000-kW. Gas Turbine Test ...	October	132
Propeller. Screw	July	95	Reverse Reduction Gearing. Large	May	64
Propeller. Tests with the Schnitger ...	June	76	Rigid Plates. Determination of Moments in	July	92
Propellers. Design and Manufacture of			Rivets. Cold Driven Large Aluminum ...	July	99
Ships'	January	15	Rolling on Properties of Steel Plates. Effect		
Propellers. Manufacture of Ship	February	23	of Direction of	December	164
Propellers. Optimum Single	October	134	Roots' Blower. Compression Work in ...	June	77
Propellers. Tests on Variable Pitch... ..	October	136	Rope. Effect of Freezing on Manila ...	January	1
Propellers. Towboat with Variable Pitch ...	July	88	Rope. Polyamide-clad Wire... ..	March	35
Propelling Machinery Progress	February	24	Rotating Disks in Pure Sliding	January	7
Propulsion Gears. Materials for	August	102	Rotor for Gas Turbine. Cooled	May	57
Propulsion Plant. Unusual	August	104	Rotor. Influence of Support upon Critical		
Propulsive Power. Resistance and	March	32	Speed of	February	24
Protection by Metallizing. Corrosion ...	May	72	Rotor Inspection. X-ray Equipment for		
Protection of Inactivated Ship Bottoms ...	June	73	Gas Turbine	December	168
Protective Coatings on Metals	February	20	Rubber to Aluminium. Bonding	November	147
Protective Coating. Refractory Ceramic ...	December	166			

	Issue	Page		Issue	Page
Rubber Packing for Pumps. Graphite Impregnated	February	22	Small Gas Turbine	February	21
Rudder". First Vessel with "Active Rudders. Towboat with Nine	September	119	Small Gas Turbine	October	132
Rules. Bureau Veritas	May	67	Small Icebreaker	August	103
Rupture Test for Tubing. Stress	January	12	Small Ship with Novel Equipment	November	152
Russia. Danish-built Tanker for	July	91	Smoke Nuisance. Stack Design to Avoid	March	39
Russia. Denmark and Holland to Build Ships for	September	127	Smooth Plane Surfaces in Turbulent Flow	July	88
Rust Protection. New Method of	April	50	Solid Fuel Fired Gas Turbine Plant... ..	October	140
	March	38	Soviet Union. Italian Ships for	November	156
			Spark Machining Hard Metals	September	117
			Spray Testing of Metals. Sea Water	January	16
			Sprayed Aluminium Coatings	September	118
			Sprayed Asbestos Insulation	March	42
			Spraying. Application of Ultrasonics to Metal	July	92
Safe Practice in Oxyacetylene Welding	January	7	Spraying Process. New Uses of Metal	March	41
Safety Valve. Improved	March	41	Spring Failures by Corrosion... ..	September	118
Safety Valve. Steam... ..	April	45	Springs. Calculation of Rectangular Bar Helical	July	90
Salvage Tug. Deep Sea	April	47	Stack Design to Avoid Smoke Nuisance	March	39
Saturated Water. Metastable Flow of	January	15	Stage-type Boilers. Desuperheater for	May	69
Saturated Water. Thermodynamic Properties of	July	92	Stainless Clad Steels	May	70
Scale Fuel Losses. Boiler	August	112	Standard Fuel. Boiler-oil as	March	33
Scandinavian Ship. Largest	May	69	Standards. Basic Engineering	September	118
Scandinavian Vessel. Largest	September	115	Starting. Diesel Engine	June	80
Scantlings of Long Deckhouses of Aluminum Alloy	July	97	Starting-air Valves	November	149
Scavenging Pump and Turbo Blower. Werkspoor Engine with	February	21	Statistical Study of Ship Motion	April	52
Scavenging System. Improved	September	124	Stayed and Unstayed Masts. Tests on	December	160
Schnitger Propeller. Tests with the Schuyler Otis Bland. Performance of s.s.	June	76	Steam and Gas Turbine. Combined	December	165
Scoop. Problem of the Condenser	June	83	Steam Boiler Materials. Testing of... ..	July	86
Screw Propeller	December	160	Steam Flow through Turbine Nozzles and Blading	August	102
Scuffing. Gear... ..	July	95	Steam Oil Atomizers	July	94
Sea Water Spray Testing of Metals	October	139	Steam Pipe Materials for Advanced Steam Conditions	June	83
Seatrains Vessels. New	January	16	Steam Power Stations. Centrifugal Pumps in	May	66
Self-sealing One-way Bolt	February	28	Steam Safety Valve	April	45
Self-unloading Bauxite Carrier	March	33	Steam Separators for Ships' Whistles	February	28
Separators for Ships' Whistles. Steam Service Performance of Gear Lubricants. Prediction of	December	167	Steam Trap	July	97
Shaft Drive for Generators	February	28	Steam Turbine Propulsion Plant. German Steamship. New Cross-Channel	February	18
Shaft. Failure of a High Pressure Turbine	December	160	Steamship. Timber-carrying	May	57
Shaft Failures. Reducing	February	19	Steamship. Velox-boilered	December	158
Shaft Materials in Torsion	June	75	Steamship with Bauer-Wach Turbine	September	114
Shaft Rotation Indicator	May	62	Steel Beams. Inelastic Strains in	May	60
Shafting. Fracture of Marine	March	41	Steel Beams. Residual Stress and Yield Strength of	July	100
Sheerstrake in Tankers. Bent Plate	August	104	Steel. Microstructure of Ship Plate	July	90
Shepers Davits... ..	March	39	Steel Beams. Plastic Flexure of	April	56
Ship Corrosion Due to Bacterial Action	December	159	Steel Pipe. Arc Welding of Low Chromium-molybdenum	February	18
Ship Fracture Problem	June	77	Steel Plates. Effect of Direction of Rolling on Properties of	November	145
Shipbuilding Material. Aluminium as Shortcomings of Structural Analysis	May	72	Steel Tubing. Reinforced	December	164
Shrink Fits in Crankshafts. Failure of	July	96	Steels. Creep of Superheater and Pipe	October	130
Sigma Welding of Carbon Steels	May	70	Steels. Sigma Welding of Carbon	December	162
Signals. Underwater Sound... ..	January	6	Steels. Stainless Clad... ..	March	35
Simple 400-horsepower Gas Turbine	October	129	Steering Control System. New	May	70
Singing in Water. Vanes	March	35	Steering Engine Accident	February	19
Single-pole Electric Circuits on Passenger Vessels	October	134	Steering Gear Control Transmission Systems	January	14
Single Propellers. Optimum	May	68	Steering Gear for Trawler	July	93
Single-screw Cargo Liners. High-powered... ..	November	155	Stiffened Panels. Fatigue Strength of	September	120
Single-screw Motor Tug	December	158	Stiffened Plating under Bending Loads. Effective Breadth of	October	130
Single-screw Motorship	December	159	Straightening Structural Members in Place	March	32
Single-screw Motorship <i>Ebro</i>	July	98	Strain Gauge. New Electric Resistance	August	102
Single Screw Vessels. Vibration of... ..	March	43	Strain Hardening. Plastic Theory Applied to	May	72
Six-bladed Propeller	January	8	Strains in Steel Beams. Inelastic	February	18
Size and Speed of Tankers	October	139	Strength of Steel Beams. Residual Stress and Yield	July	100
Slagging. Oil Additive to Relieve Boiler	September	128	Strengthening of T2 Hulls	July	90
Sleeve Bearing Performance	September	128	Stress and Rating Formulæ. Gear-tooth	September	125
Sleeve Bearings. Foreign Particles in	September	128		April	49
Slow Precession of a Gyroscope. Motion Due to	June	74			
Sludge Vessel. New	April	55			

	Issue	Page		Issue	Page
Stress and Yield Strength of Steel Beams.			Testing. Corrosion	March	42
Residual	July	90	Testing of Metals. Sea Water Spray	January	16
Stress Finder for Ship's Loading	September	121	Testing of Steam Boiler Materials	July	86
Stress from a Marine and Naval Viewpoint.			Testing Welds by Bulge Explosion Test	February	19
Studies of Human	June	74	Thermal Conditions in H.M. Ships in Tropical Waters	June	83
Stress Relief Treatment of Welds	July	98	Thermodynamic Properties of Saturated Water	July	92
Stress Rupture Test for Tubing	July	91	Thickness Testing. Ultrasonic	December	166
Stresses in Welded Mild-steel Pipe. Residual	January	2	Tilting pontoons	October	138
Structural Action of Superstructures	September	115	Timber-carrying Steamship	December	158
Structural Analysis. Shortcomings of	January	6	Titanium. Advantages of	October	129
Structural Members in Place. Straightening	August	102	Titanium. Corrosive Resistance of	September	118
Structural Parts. Minimum Weight of	March	31	Tooth Wear. Gear	October	139
Stud Welding Cast Iron	March	35	Torch as Drill. Use of Welding	June	77
Stud Welding on Aluminium Alloys	January	2	Torch. Compressed Air Arc... ..	May	71
Studies of Human Stress from a Marine and			Torsion. Shaft Materials in... ..	March	41
Naval Viewpoint	June	74	Torsional Vibration of Flexible Coupling	December	161
Study of Buckling Problems	October	130	Torsional Vibration Recorder... ..	September	114
Sulphurous Fuels for Diesel Engines	September	116	Towboat with Nine Rudders... ..	May	67
Sulzer Diesel Engine Features. New	November	146	Towboat with Variable Pitch Propellers	July	88
Supercharged M.A.N. Diesel Engine—(I).			Towing Tests	October	137
Highly	May	58	Two 1,660 b.h.p. Auxiliary Engines for Liner	January	13
Supercharged Two-stroke Engine. Werk-			Tracers. Measurement of Ventilation by		
spoor	August	105	Radioactive	July	92
Superheat Control	March	44	Transmission. Fluids for Hydraulic Power	January	7
Superheater and Pipe Steels. Creep of	December	162	Transmission Systems. Steering Gear Con-		
Superstructures. Structural Action of	September	115	trol	July	93
Support upon Critical Speed of Rotor.			Trap. Steam	July	97
Influence of	February	24	Transport Vessel. Air Conditioned Troop... ..	September	126
Suppressing Crankcase Explosions	August	108	Trawl Winch	June	84
Surface Condition. Chemical Behaviour as			Trawl Winch. Hydraulically Controlled	September	122
Influenced by	December	166	Trawler. Diesel	September	127
Surface Defects. Non-destructive Investiga-			Trawler. Fishery Research	June	75
tion of	December	164	Trawler. Steering Gear for	September	120
Surface-dependent Phenomenon. Creep as a			Trawler's Fishroom. Design of	September	120
Swedish Ferry. New	January	15	Trawlers. Drifter	April	48
Swedish Ice-breaker	January	2	Trial. Tanker	May	69
Swiss Lake Motorship	June	74	Troop Transport Vessel. Air Conditioned	September	126
Swedish Liner. Funnels for New	March	36	Tropical Waters. Thermal Conditions in		
Swiss Cargo Motor Ship	November	148	H.M. Ships in	June	83
Swiss Motorship	December	161	True Water Level in Boiler	September	113
	September	128	Tube Joints. Ceramic Backing for	September	116
T2 Hulls. Strengthening of	September	125	Tube Plates for Heat Exchangers. Design		
Tank Cleaning. New Method of	June	76	of	July	98
Tank Coatings. Corrosion Resistant	September	118	Tubes. Heat Transfer Inside	February	22
Tank Coatings. Gasolene Resistant... ..	June	73	Tubing. Reinforced Steel	October	130
Tanks. Venting Cargo Oil	January	6	Tubing. Stress Rupture Test for	July	91
Tanker Built in Japan... ..	April	53	Tug. Deep Sea Salvage	April	47
Tanker for Russia. Danish-built	September	127	Tug. Twin Screw Motor Pusher	July	89
Tanker. Largest	July	98	Tug with Unusual Propulsion	July	97
Tanker. Largest Motor	July	98	Tugs. Propeller Design for	September	120
Tanker Lines. New Clamp for	September	115	Tugboat. Unusual	January	16
Tanker Load Calculator. Götaverken	January	11	Turbine. Allen Gas	January	2
Tanker. Norwegian	December	168	Turbine Blade Vibration. Gas	November	147
Tanker Trial	May	69	Turbine. Combined Steam and Gas	December	165
Tanker's Low Fuel Consumption. Motor	May	65	Turbine Control. Gas	October	132
Tankers. Bent Plate Sheerstrake in... ..	December	159	Turbine. Cooled Rotor for Gas	May	57
Tankers. Bulkhead Intersections for Welded			Turbine Drive. Gas and Hydraulic	January	7
Tankers. Centrifugal Cargo Pump for	July	88	Turbine. Features of 250-kW. Marine Gas	March	36
Tankers. Combating Corrosion in	July	100	Turbine for Cargo Vessel. Gas	March	34
Tankers. Diesel Engines for Large	February	24	Turbine from the Viewpoint of an Aero-		
Tankers. Large	February	20	nautical Engineer. Marine Gas... ..	March	36
Tankers. New Super	July	91	Turbine. Inward-flow Radial Gas	December	164
Tankers. Size and Speed of... ..	January	8	Turbine. Light-weight Gas... ..	October	131
Temperature Service. Aluminium Alloy for			Turbine Lubricating System. Cleaning		
Elevated	November	142	Marine	August	103
Test Plant. Dynamometers and Engine	September	116	Turbine Nozzles and Blading. Steam Flow		
Test Plant. U.S. Navy Expands Boiler	June	81	through	August	102
Tests on Stayed and Unstayed Masts	December	160	Turbine Operating Experience. Gas	December	165
Tests on Variable Pitch Propellers	October	136	Turbine Plant in 1951. Marine Gas	March	38
Tests of Werkspoor-Lugt Engine	January	5	Turbine Plant. Solid Fuel Fired Gas	October	140
Tests with the Schnitger Propeller	June	76			
Testing. Coupon Technique in Corrosion... ..	June	73			

	Issue	Page		Issue	Page
Turbine Progress. Gas	October	132	Vibrations. Analysis of Ship	January	16
Turbine Rotor Inspection. X-ray Equip- ment for Gas	December	168	Vibrations in Marine Engineering	February	24
Turbine Shaft. Failure of a High Pressure	June	75	Vibrations of Thin Cylinders. Flexural ...	October	130
Turbine. Simple 400-horsepower Gas ...	March	37	Victory and C-3 Ships. New Propeller Designs for	October	135
Turbine. Small Gas	February	21	Voith Schneider Propeller. Control Device for	November	141
Turbine. Small Gas	October	132	<i>Waimate</i> . Geared Motorship	January	12
Turbine. Steamship with Bauer-Wach ...	May	60	Water. Electrical Pretreatment of	September	125
Turbine Test. Results in 1,000 kW. Gas ...	October	132	Water Level in Boiler. True... ..	September	113
Turbines. Combustion in Gas	April	52	Water. Metastable Flow of Saturated ...	January	15
Turbines. Latest Geared	August	109	Water. Thermodynamic Properties of Saturated	July	92
Turbines of 1,500 s.h.p. Geared	August	107	Water. Vanes Singing in	September	122
Turbine Propulsion Plant. German Steam	February	18	Wave Recorder in Research Ship	July	96
Turbo Blower. Werkspoor Engine with Scavenging Pump and	February	21	Waves of Ships. On the	November	156
Turbo-charged Doxford Engine	September	123	Wear. Effect of Lubrication and Forms of	December	162
Turbulent Flow. Smooth Plane Surfaces in	July	88	Wear. Gear Tooth	October	139
Twin Arc Welding Process	July	90	Weight of Structural Parts. Minimum ...	March	31
Twin-screw Cable Steamship... ..	October	136	Welds by Bulge Explosion Test. Testing ...	February	19
Twin-screw Cargo Liner	August	112	Welds. Stress Relief Treatment of	July	98
Twin Screw Motor Pusher Tug	July	89	Welded Construction. Relation of Notch Bar Testing to... ..	March	29
Twofold Use of Magnetic Couplings ...	February	22	Welded Mild-steel Pipe. Residual Stresses in Welded Pipe Joints between Dissimilar Materials	January	10
Two-furnace Boiler	May	65	Welded Ship Building	September	127
Two-stroke Marine Diesel Engine	September	125	Welded Ships. Observations on Experience with	November	143
Two-stroke Engine. Werkspoor Supercharged	August	105	Welded Tankers. Bulkhead Intersections for Welding. Argon Arc... ..	May	63
Ultrasonic Flaw Detector. New	July	93	Welding Cast Iron. Stud	May	70
Ultrasonic Thickness Testing... ..	December	166	Welding of Carbon Steels. Sigma	March	35
Ultrasonics to Metal Spraying. Application of	July	92	Welding of Low Chromium-molybdenum Steel Pipe. Arc	November	145
Underwater Sound Signals	October	134	Welding on Aluminium Alloys. Stud ...	January	2
Unloading with Air-activated Gravity Con- veyors. Vessel	February	17	Welding Process. Twin Arc... ..	July	90
Unstayed Masts. Tests on Stayed and ...	December	160	Welding. Safe Practice in Oxyacetylene ...	January	7
Unusual Propulsion Plant	August	104	Welding Torch as Drill. Use of	June	77
Unusual Tugboat	January	16	Werkspoor Engine with Scavenging Pump and Turbo Blower	February	21
U.S. Navy Expands Boiler Test Plant ...	June	81	Werkspoor-Lugt Engine. Tests of	January	5
Use of Detergent Lubricants... ..	March	33	Werkspoor Supercharged Two-stroke Engine	August	105
Use of Welding Torch as Drill	June	77	Wet Compression in Axial Flow Compressor	October	131
Vacu-Blasting	December	166	Wet Weather. Cargo Handling in	February	27
Vacuum Brazing. High Strength	December	162	Wheelhouses and Bridges. Design of ...	April	50
Valve. Improved Safety	March	41	Whistle. Electronic Ship's	September	114
Valve. Steam Safety	April	45	Whistles. Steam Separators for Ships' ...	February	28
Valves. Starting-air	November	149	Winch. Dynamic Selector	October	135
Vanes Singing in Water	September	122	Winch. Hydraulically Controlled Trawl ...	September	122
Vapour Phase. Engine Cooling with ...	November	150	Winch. Trawl	June	84
Vapour Washers for Evaporation	November	152	Winch with Electric-hydraulic Drive ...	February	24
Variable Pitch Propellers. Tests on... ..	October	136	Wire-rope Clamping System. New... ..	August	103
Variable Pitch Propellers. Towboat with ...	July	88	Wire Rope. Polyamide-clad	March	35
Variations of Fast Coasters. Form	May	67	X-ray Detection of Flaws in Metal	December	163
Vee-type Diesel Machinery. Pressure-charged	May	65	X-ray Equipment for Gas Turbine Rotor Inspection... ..	December	168
Velox-boilered Steamship	September	114	Yield Strength of Steel Beams. Residual Stress and	July	90
Ventilation by Radioactive Tracers. Measure- ment of	July	92	Zinc Coating Process. New	November	147
Ventilation Pressure Control	July	99			
Venting Cargo Oil Tanks	January	6			
Vessel Unloading with Air-activated Gravity Conveyors... ..	February	17			
Vibration. Damage Due to	February	20			
Vibration. Gas Turbine Blade	November	147			
Vibration of Flexible Coupling. Torsional	December	161			
Vibration of Single Screw Vessels	July	98			
Vibration Recorder. Torsional	September	114			